

Scarboro Toyota  
297 Scarborough Beach Road,  
Osborne Park, WA 6017

T 08 9273 1000  
F 08 9273 1032  
service@scarborotoyota.com.au  
scarborotoyota.com.au

BSB 016002 ACC 838368335  
ABN 61 008 729 468 ACN 008 729 468  
DL1761 MVRB3355

ARC AU41333



Scan to get a Toyota Genuine Insurance\* Quote

\*Toyota Insurance is issued and underwritten by Aoi Nissay Dowa Insurance Company Australia Pty Ltd (Adica) ABN 11 132 524 282 AFSL 443540. Before purchasing a policy please read the Product Disclosure Statement to determine if this product is right for you. A Target Market Determination for this product is also available. Both documents are available at toyotainsurance.com.au

REPAIR ORDER No <b>JC24218173</b>	PAGE <b>1</b>
C1 Customer (Cash)	

Guest <b>MR JINGYANG LI</b> 9 Kimber St INNALOO WA 6018		DATE 23/02/2024	TIME IN 9 10 AM	TIME OUT 3 30 PM	KILOMETERS 123103	ADVISER TM
VEHICLE COROLLA HATCH 2.0L 4cyl Pet CVT Ascen				MONTH/YEAR 11/2018	AIR	
REG No 1HAM867	STOCK No U110496	SELLING DEALER				
GUEST No 93147	VIN JTNK43BEX03024825			ENGINE No M20A5080052		
CONTACT NAME Jay Li		COLOUR/TRIM Glacier White/Black Fabric			ORDER No	
CONTACT NUMBERS M 0450791868		WAR EXP	WAR KM	EXT WAR EXP 31/10/2024	EXT WAR KM 999999	RDR Date 19/11/2018

JOB DETAILS		PRICE	QTY/HSR	AMOUNT
JOB 1	Carry out 108 months/135,000km service, Toyota Service Guarantee Carried out 108 months/135,000km service, Toyota Service Guarantee Includes - Replaced engine oil & oil filter. Inspected drive belt Inspected radiator & condenser for debris & signs of damage Inspected cooling system, hoses & connections Inspected battery electrolyte, cleanliness & security Replaced air filter element Checked brake pedal height & hand brake lever operation Inspected brake pads & discs Inspected brake fluid Checked brake pipes & hoses Inspected steering wheel, gear & linkages Inspected drive shafts including CV boots Inspected ball joints & dust covers Inspected automatic transmission fluid Inspected towbar & nudge bar mounts (if fitted) Checked condition & pressures of all tyres including spare Rotated wheels Checked lights, wiper/washers, horn & electrical systems Inspected all seat belts operation and condition Inspected driver's floor mat for correct fitment and retention Road tested vehicle & reported any defects			182 00
PRT	TOY 0888800001C	ORD P/N 0888800001EP	1	90
PRT	TOY 1780177050	ELEMENT SUB-ASSY	1	36 56
PRT	TOY 9043012031	GASKET	1	1 95
PRT	TOY 9043018008	GASKET	1	2 11
PRT	TOY 90915YZZN2	OIL FILTER 65*72	1	26 01
CON	Toyota Motor Oil			41 68
MIS	Miscellaneous Other Supplies			21 54
<b>JOB 1 SUBTOTAL</b>				<b>312.75</b>

<b>JOB DETAILS</b>	JOB 2 CARRY OUT FRONT WHEEL ALIGNMENT	77.27
--------------------	---------------------------------------	-------

\*\*\*\*\* CONTINUED \*\*\*\*\*

VEHICLE RELEASE <input type="checkbox"/> WORK EXPLAINED <input type="checkbox"/> VEHICLE WASHED <input type="checkbox"/> FLOOR MAT SECURITY EXPLAINED <input type="checkbox"/> COST EXPLAINED <input type="checkbox"/> ALL COURTESY ITEMS REMOVED		PREFERRED CONTACT METHOD <input type="checkbox"/> LETTER <input type="checkbox"/> PHONE <input type="checkbox"/> DO NOT CONTACT <input type="checkbox"/> EMAIL <input type="checkbox"/> MOBILE/SMS	
DELIVERED BY _____ DATE _____ RECEIVED BY _____ TIME _____	<input type="checkbox"/> CASH <input type="checkbox"/> ACCOUNT <input type="checkbox"/> EFTPOS/CREDIT CARD		
AMOUNT RECEIVED WITH THANKS _____		RECEIVED BY _____	