

Service TAX Invoice		Page 1 of 3		Doc #: HYCS378385			
Customer No. 107439	Customer Name & Address Morgan Le Guludec 119 Market Road  Werribee VIC 3030			Advisor ANTHONY CASSAR 0779	Colour	Team Werribee	
Doc. Date 24/01/24				Year / Make / Model 14/HYUNDAI/H-1 iMax 5Dr WL8 LWB Wagon 2.5		Tag No. B10/	
Reg. No. 1BL6YB				Model No. GDB86B85D	Carline		Eng./Trans.
Stock No.				Chassis No. KMHWH81KMEU628257	Kilometres 260039	Prod. Date 25/01/14	Orig. Del. Date 09/04/14
Purchase Order No.	Driver	Mobile No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH	Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 09/04/14	Warr. Exp. Date 08/04/19
<input type="checkbox"/> CREDIT CARD	Vehicle ID. KMHWH81KMEU628257		Engine No. D4CBE448274	Date & Time Promised 24/01/24 04:00pm	Time Received 08:00am	Quote Price	Air Pwr Turbo
<input type="checkbox"/> ACCOUNT							
Cust Mobile 0490354852	Drivers Mobile		Priv Code	Reg Exp Date			
Home Email morgan.leguludec@gmail.com	Bus. Email		Drivers Email	Next Svc Date			

Labour	Operation	Description	Amount
--------	-----------	-------------	--------

Job#	1	01HY35365ICES01	Tech(s): 0771	180.41
------	---	-----------------	---------------	--------

Carry out Hyundai iCare Essential Service

Carried out 255,000 km service

Battery Test - Good health

Express wash and vacuum of floor mats only

Customer Instructions:

Carried out Hyundai iCare Essential Service.  
Checked vehicle for outstanding recall or service campaigns.  
Carried out complete Global Diagnostic System (GDS) check.  
Checked instrument cluster & warning lights.  
Inspected seat belts.  
Checked lights, wiper/washers, horn & electrical systems.  
Inspected battery electrolyte, cleanliness & security.  
Replaced engine oil & oil filter.  
Inspected drive belt/s.  
Inspected fuel system lines & connections.  
Inspected cooling system including radiator & hoses.  
Inspected brake lines & hoses.  
Inspected brake pads, calipers & discs.  
Inspected park brake operation & adjusted as required.  
Inspected power steering system.  
Inspected steering gear, linkage & boots.  
Inspected suspension for damage/wear & torqued all mounting points.  
Inspected exhaust system for security, leaks & damage.  
Checked condition & pressures of all tyres including spare.  
— Additional Charges Apply if Replacement is Required —  
Inspected automatic transmission fluid.

Checked air filter.

HY2151323001	GASKET-OIL PLUG	1	3.83
HY263304A001	FILTER ASSY-ENGINE OIL	1	46.97
POL	MAGNATEC PRO MPDX 5W30		74.00
POL	CARWASH ALLOWANCE		0.00
POL	HYUNDAI ROADSIDE ASSIST - No Charge		0.00
Misc: WS	WORKSHOP SUPPLIES		8.00
Misc: WASTE	OIL ENVIRONMENTAL DISPOSAL CHARGE		5.00

EFT Details: BSB - 083909 Acct - 517314547

\*D0070005\*

**WERRIBEE HYUNDAI**

163-179 Old Geelong Road  
 Hoppers Crossing 3029  
 P.O. Box 59, Werribee 3030  
 Service Direct: 9974 4902 General Enquiries: 9974 4900 F: 9974 4901  
 A.B.N. 98 054 957 587 LMCT 114  
 www.werribeehyundai.com.au



Licensed Air Conditioner Repairer  
 Arctick RTA # AU03088

Service TAX Invoice				Page 2 of 3				Doc #: HYCS378385								
Customer No. 107439	Customer Name & Address Morgan Le Guludec 119 Market Road			Advisor ANTHONY CASSAR	Colour 0779	Team Werribee		Year / Make / Model 14/HYUNDAI/H-1 iMax 5Dr WL8 LWB Wagon 2.5		Tag No. B10/						
Doc. Date 24/01/24	Reg. No. 1BL6YB			Model No. GDB86B85D		Carline		Eng./Trans.		Stock No. Werribee VIC 3030						
Purchase Order No.	Driver	Mobile No.		Contract Name		Contract Exp. Kms	Exp. Date		Chassis No. KMHWH81KMEU628257		Prod. Date 25/01/14	Orig. Del. Date 09/04/14				
<input type="checkbox"/> CASH	Home Phone	Business Phone	Terms Cash	Selling Dealer		Delivery Kms.	Delivery Date 09/04/14	Warr. Exp. Date 08/04/19		Date & Time Promised 24/01/24 04:00pm		Time Received 08:00am	Quote Price	Air	Pwr	Turbo
<input type="checkbox"/> CREDIT CARD	Vehicle ID. KMHWH81KMEU628257		Engine No. D4CBE448274	Date & Time Promised 24/01/24 04:00pm		Time Received 08:00am	Quote Price	Air	Pwr	Turbo	<input type="checkbox"/> ACCOUNT					

<<< Total For Job 1 >>>

318.21

Job# 2 10HY Body - Base Tech(s): 0771 No Charge  
**C/S: check suspicious noise around the front shock absorber driver side**  
*Check and found the front lower arm bolts were loose  
 Found non genuine bushes in front lower arms  
 Performed retightening of the lower arm bolts, tested and all ok*

Job# 3 13HYWALG Wheel Alignment Tech(s): 0629 68.18  
**Align all Wheels to Manufacturer's Specifications**  
 Performed Wheel Alignment to Manufacturer's Requirements

<<< Total For Job 3 >>>

68.18

Misc: RO 1 & 2 CENT ROUNDING

-0.03

**Comments**

STCHECKIN : #B10 Uber there is a suspicious noise around the front shock absorber, driver side, can you please have a look at it?

**Recommendations**

Front Brakes have approximately 9.0 mm friction material remaining  
 Rear Brakes have approximately 9.0 mm friction material remaining  
 Front Tyres have approximately 6.5 / 6.5 mm tread remaining  
 Rear Tyres have approximately 4.5 / 4.5 mm tread remaining  
 Recommendations :  
 EGR pipe + gaskets - \$940 (sydney)  
 Wipers - \$55  
 Globes - \$60

Total Labour	248.59
Total Parts	50.80
Total POL	74.00
Total Sublet	0.00
Total Misc	12.97
Total Tax	38.64

TOTAL AMOUNT INCLUDING GST

Total Invoice 425.00