

## TAX INVOICE

Tax Invoice Number: 1617

Date: 16/10/2023 Due Date: 16/10/2023

544 Sturt Street

Townsville Queensland 4810

**ABN:** 24749252865 **Tel:** 07 4771 3078

Email:

admin@empirevehicleservices.com.au

BILL TO: Huiqi Huo

Tel: 0423 952 125

Email: vickeyfok@gmail.com

FOR:

Major Service

Odometer: 158,168 Kms

Make	Model/Year	Body Type	Reg No. Fleet No.	VIN
SUZUKI	GRAND VITARA/2017	STATION WAGON	838BL8	JSAJTAA4V00360155

Description	Qty.	Unit Price	Amount
LBS4CYLM-S - Logbook Service 4 Cylinder Major Synthetic	1.0	\$427.27	\$427.27
Oil and filter	-	•	,
Inspect air filter			
Safety inspection			
Lube door hinges			
Spray protectant on battery terminals			
Add additive to windscreen washer bottle			
Rotate tyres			
Check all fluids			
Clean engine bay			
Complementary car clean and vacuum			
Clean all sensors			
Pressure test cooling system to check for possible leaks			
Load test battery			
Check spark plugs and re gap if necessary			
Remove intake pipe and clean throttle body			
Remove and inspect cabin filter			
Add injector cleaner			
OMTR610-20 - WIPER BLADE INSERT 6 x 610mm METAL RAIL	2.0	\$6.82	\$13.64
RCA165P - RYCO CABIN AIR FILTER - POLLEN	1.0	\$57.73	\$57.73

- Transmission mount is sagged	and touching	the bump sto	p. Recommend
replacing			

- Front diff mount bush is split. Recommend replacing
- Both rear shocks are leaking. Recommend replacing
- Both strut tops are clicking when turning. Recommend replacing
- Coolant overflow bottle was empty. Radiator cap T piece is damaged not allowing us to pressurise the cooling system. Recommend replacing T piece and pressure testing the cooling system to check for possible leaks
- Handbrake requires adjusting
- Rocker cover is leaking oil, only minor. Have tightened bolts and degreased. Not yet an issue, recheck next service
- Battery failed load test at 80%. Vehicle seems to start okay. Recheck next service
- Rear diff bushes are starting to split. Not yet an issue, recheck next service
- Drivers front seat belt retracts slowly

Subtotal	\$498.64
GST	\$49.86
Total	\$548.50
Paid	\$548.50
Balance Due	\$0.00

Empire Vehicle Services
BSB - 654 000
ACC - 6419 2040
Please use invoice number for description

Please like our Facebook and leave a review on Google