



be safe. be sure

TAX INVOICE
I-54417
05 Mar 2024

ABN 84 101 369 180

Brett Tsudama
22/25 Addison Rd
Manly NSW 2095

Job J-58672
11/10 Mazda 2
BTO86Z

Tel (02)
Mob 0429 868 294

Odometer 106051

W O R K t o b e D O N E

Gold Minor Service
Head Light Globe
Refit Floor Mat Clip
Front Disc Brake Pads
Wheel Balance Rotation
Front Wheel Alignment

W O R K D O N E

Gold Minor Package, apply engine and fuel system cleaning additives, grease, oil change and fluid level checks. Replace oil filter, run engine, check for leaks. Pressure test cooling system, check condition of hoses, clamps, and coolant. Check security and condition of exhaust system, front and rear suspension and steering components. Lubricate and inspect transmission linkages. Check drive train components. If necessary remove and replace road wheels to inspect and adjust front and rear brakes including hand brake. Inspect accessory drive belts. Check tyre pressures including spare tyre and adjust as necessary. Check operation of all lights and indicators, horn, windscreen wipers and washers. Comprehensive mechanical inspection, 70 point safety check and report. Reset vehicle computer/ service light (as required).

160.00

Remove and replace near side head light globe and test operation.

15.00

Remove wheels to remove front calipers and disc pads. Measure front disc rotors and check minimum thickness. Lubricate caliper piston and slides/unseize slides. Retract caliper pistons and refit new disc pads with antisqueal. Re-assemble, bleed and road test to initiate bedding in process.

160.00

Remove four wheels, check rims and tyres for run-out and

INVOICE Total \$813.15
Continues...

balance. Adjust tyre pressures. Balance four wheels. Pick best position for wheels and replace on vehicle rotating as required. 80.00

LABOUR Total \$415.00

P a r t s a n d M a t e r i a l s

| Qty | Pkg | Part No. | Description | Price |
|-----|-----|-----------------|--------------------------------|--------|
| 1 | EA | WS/WINDOWWASHER | Windscreen washer additive | 2.50 |
| 2 | ea | WS/WORKSHOPSUP | Wshop Sup/Enviro Levy/TechData | 39.10 |
| 1 | EA | AD/8101.20/VAL | Injector and Carby Cleaner | 15.13 |
| 1 | EA | AD/8124.20/VAL | Engine Flush | 13.24 |
| 1 | EA | OF/Z436/KEN | Oil Filter | 15.41 |
| 3.9 | EA | FL/1030.57/TLC | Valvoline Pro Series 10W-30 | 63.80 |
| -1 | EA | VIP | VIP Discount | -19.70 |
| 1 | EA | GL/H4/B&S | Headlight Globe | 17.73 |
| 1 | EA | DB1941GCT | Brake Pad Set | 107.00 |

PARTS Total \$254.21

S U B L E T R E P A I R

Set up alignment heads and carry out computer front wheel alignment to manufacturers specifications. Test drive vehicle. 70.00

SUBLET TOTAL \$70.00

T O T A L S

| | | |
|------------------------|-----------------------|-----------------|
| Print Time 14:14:36 | Labour | \$415.00 |
| Print Date 05 Mar 2024 | Parts | \$254.21 |
| Job J-58672 | Sublet | \$70.00 |
| Cust Copy No. 1 | General | \$0.00 |
| POSTED Invoice | GST 10% | \$73.92 |
| | Rounding | \$0.02 |
| | Total incl GST | \$813.15 |

Quality workmanship guaranteed

Continues...

Autolab
Customer Copy

Page 3
Job J-58672

Brett Tsudama
22/25 Addison Rd

Rego : BTO86Z
Make : Mazda
Model : 2
Year : 11/10

Manly NSW 2095

Odometer : 106051
Date : 04 Mar 2024

R E P O R T

100% of front and 30% of rear brake material remaining.

90% of front and 75% of rear tyre tread remaining.

Battery condition good.

Following requires attention:

Urgent:

-

Non-Urgent

-
