

Barry Cooper Auto Repairs

82 Federal Street
North Hobart TAS 7000

ABN 88 009 542 376
Tel: 03 6234 2243 Fax: 03 6234 2482
Email: bcar@eftel.net.au
Website: www.repcoservice.com
After hours 0418882043



Tax Invoice

Invoice No. 35732 **Date** 3/4/2024 **Sales ID** Hurd. Zack

Client details

Weining Li
33 Cribb AVE
Mitchelton 4053

Vehicule Details

Registration F59WR **ODO** 290735
Make/Model: Toyota RAV4
Year 2017

JOB DETAILS

Carry out 137,500km service as per handbook
Includes Replaced engine oil & oil filter
Inspected drive belt
Inspected battery electrolyte, cleanliness & security
Inspected brake fluid
Checked power steering fluid
Checked condition & pressures of all tyres including spare.
Checked lights, wiper/washers, horn, lights & electrical systems
Inspected all seat belts operation & condition
Road tested vehicule & reported any defects.

PARTS

Gasket	1	\$1.95
Oil filter	1	\$28.55

Consumables

Engine oil 5W-30		\$75.00
	Labor	\$88.40
	Miscellaneous	\$20.00

Notes:

Subtotal	\$213.90
GST	\$21.39
Total	\$235.29