



TAX INVOICE

Tax Invoice Number: 3282
Date: 09/11/2023
Due Date: 09/11/2023

281 Homer Street
Earlwood New South Wales 2206
ABN: 97644560574
Licence: MVRL 58250

BILL TO:
Brendan
Tel: 0400804624
Email: smithbrendan32@hotmail.com

FOR:
Radiator Replacement
Odometer: 280,463 Kms
Model: Toyota Hiace
Reg No: AR47TK
Next Service Date: 28/05/2024
Next Service Odometer: 288,584 Kms
Year: 2007

BANKING DETAILS:
ACE MECHANIX
BSB: 012286
ACC NUMBER: 321 463 049
PAY ID: 0403 900 087

Tel: (02) 8084 4494
Fax: 0403900087
Email: info@acemechanix.com.au
Website: www.acemechanix.com.au

Description	Qty.	Unit Price	Amount
Supply and fit complete reconditioned engine with 12 months warranty or 20,000kms			
total	1.0	\$9,500.00	\$9,500.00
Radiator Replacement			
Remove Radiator hoses, fan unit and any oil lines connected to radiator, remove and refit radiator support bracket's. Install new radiator and reassemble all parts. Fill with required coolant pressure test for any leaks and run engine untill radiator completely bleed or any air in system and cooling fans switch on to ensure temperature is operating within manufacturers specifications.			
Radiator	1.0	\$850.00	\$850.00
Labour involved to remove and replace Radiator	1.0	\$450.00	\$450.00
description			

The engine had overheated and the driver of the vehicle at the time mustn't have been paying any attention to the temperature gauge causing it to overheat to the point that the engine had seized requiring a complete overhaul motor. If proper care was taken and the motor was switched off and not driven when it overheated the engine wouldn't have needed replacement.

Subtotal	\$9,818.18
GST	\$981.82
Total	\$10,800.00
Paid	\$0.00
Balance Due	\$10,800.00