

CHAPEL AUTOMOTIVE

ABN: 68 395 088 349
 Chapel Automotive
 174 Inkerman St
 ST KILDA 3182
 ST KILDA VIC 3182
 Phone: 03 9018 9025
 Email: info@chapelautomotive.com.au



Deliver To:

Vincent Artis
 ST KILDA VIC 3182

Page 1 of 3

Account	Registration No.	Vehicle Make:	Vehicle Model:	Vehicle Year:	VIN:	Odometer:
1	1SX5QB	FORD	FIESTA	2013		109974

Date	Time	Salesperson	Order No.	Document Type	TAX INVOICE Number
27/11/23	4:20p	DANIEL ADES		TAX INVOICE	103666

Product	Description	Qty	Price	Amount
<u>W/ORDER: 010040</u>				
ZFLUSH	ENGINE OIL FLUSH	1.00	20.00	20.00
ZOIL	SEMI SYNTHETIC 10W-40	4.50	11.00	49.50
PAZ418	OIL FILTER Z418 AC024	1	17.50	17.50
PASUM	SUMP PLUG WASHER	1	3.00	3.00
ZIC	INJECTOR CLEAN/FUEL CONDITION	2	11.00	22.00
HAI1855515HD921	HAI 185/55/15 86V HD921	4	150.00	600.00
	HAIDA 185/55/15 86V HD921			
ZA2	FRONT & REAR WHEEL ALIGNMENT	1	90.00	90.00
ZPP	NEW A/C COMPRESSOR CD	1	880.00	880.00
ZPP	NEW SWAP BAR LINK SET	1	120.00	120.00
PAFB	FAN BELT 6PK1037EE	1	55.00	55.00
ZGAS	AIRCON SERVICE INC UV DYE	1	240.00	240.00

AIR CONDITIONING SERVICE

Check operation of air conditioning system and visually check for any leaks. Evacuate gas from system. Regas system with UV Dye and recheck for any leaks. NOTE: Some leaks may take a few weeks to become visible.

Refrigeration Authorisation License number: AU51673

REMOVED.. FILLED... 390

ZLS	LABOUR CHARGE FOR SERVICES	4.00	143.00	572.00
-----	----------------------------	------	--------	--------

SERVICE

Flush engine oil and change oil filter. Check cooling system and fluid levels. Check air and cabin filters, engine drive, belts and hoses. Check gearbox and differential oil levels. Check condition of exhaust, tyres, shock absorbers, suspension and lights. Check for fluid leaks. Check and adjust brakes. Rotate and balance wheels. Test battery and clean terminals. Scan and check computer and clear all fault codes. Reset Service interval. Road test and report.



*DA

REPLACE BENT FRONT SWAY BAR LINKS
AIRCON COMPRESSOR SEIZED - SUPPLY AND FIT NEW A/C COMPRESSOR AND SERVICE SYSTEM
REPLACE 4 NEW TYRES
REPLACE DRIVE BELT
REPLACE DAMAGED FRONT SWAY BAR LINKS
RECALIBRATE ELECTRIC POWER STEERING AND RESET STEERING ANGLE SENSOR

REPORT: WIPERS
LEFT REAR SUSPENSION DAMAGED - NOT WITHIN SPECIFICATIONS

Deposits totalling \$0.00 used for this invoice

DON'T VOID YOUR NEW CAR WARRANTY, SERVICE YOUR CAR WITH US!

PAID BY: VISA/MASTERCARD : 2669.00

NET TOTAL	2426.36
GST	242.64
TOTAL \$	2669.00

Our Banking Details CBA BSB 063 104 ACC 1043 7495



Chapel Mash Pty Ltd t/a Chapel Corner Automotive
ACN 149 779 840

"Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure."

This warranty is in addition to the rights and remedies available to you at law

The following details of the party giving the warranty:

Chapel Automotive
168-174 Inkerman Street, St Kilda VIC 3182
03 9018 9025
info@chapelautomotive.com.au

In addition to any manufacturer's warranty on faulty goods, the following products / services come with specific warranties:

Motor vehicle service / repair work is covered by a 6 month labour warranty
Any motor vehicle service / repair work containing the use of secondhand parts is covered by a 30 day labour warranty

Please contact us at the address listed above for claim assessment. We will bear the expenses of the warranty repair or replacement.

