













Your Local Autocare Professionals

TAX INVOICE I-35393 27 Mar 2024

Job J-39374 16 HYUNDAI iMAX 777XHD

Odometer 178875

WORK to be DONE

CHECK BRAKE FAULT SERVICE

WORKDONE

Carried out Log Book Service, grease, oil change and replacement oil filter, checked all under bonnet levels, checked for oil leaks. Cleaned out air filter housing and replaced air filter element, inspected air preheat system, inspected fuel system for leaks, condition of hoses and unions, inspected fuel filter. Removed 1/h lower dash trims and replaced cabin air filter. Load tested battery. Checked and adjusted tyre pressures including spare. Pressure tested cooling system, checked condition of hoses, clamps and coolant. Checked tension and condition of engine drive belts. Checked security and condition of exhaust system. Checked front suspension, rear suspension and steering components for wear, checked drive train components for wear, leaks and security. Lubed and inspected transmission linkages. Checked and topped up transmission oil levels. Removed all road wheels and inspected brake pads for wear, brake pipes and hoses for deterioration, checked condition of brake fluid and refitted wheels. Road tested vehicle to assess brake / engine performance and general driveability. Replaced 1/h headlamp bulb where blown.

Inspected rear brake pads - found to be excessively worn.

Removed brake pads and checked caliper dust seals for

deterioration and signs of fluid loss, checked caliper slides

and lubed, checked discs for wear / scoring, found to be in

INVOICE Total
Continues...

BULIMBA

51 Godwin Street Ph: 3399 8161 ABN 59 970 159 478

MILTON

36 Douglas Street Ph: 3369 1374 ABN 59 970 159 478

NEWSTEAD

18 Austin Street Ph: 3162 8122 ABN 42 630 232 156

WEST END

194 Montague Road Ph: 3180 2819 ABN 51 643 301 115

WOOLOONGABBA

100 Deshon Street Ph: 3726 9544 ABN 11 634 697 671 LE MANS MOTORS Customer Copy

need of replacement. Removed calipers complete and withdrew disc assemblies. Cleaned and inspected handbrake shoes, fitted up new brake discs, reset handbrake shoe adjustments and reassembled with new brake pads. Checked and reset fluid level in master cylinder. Road tested to "bed in", all o.k.

Replaced r/h/f, l/h/r and spare tyres, rotated so 2 new to front and best old tyre to spare. Carried out wheel alignment as required.

Checked over for brake warning light on, checked reservoir level switch, all ok. Removed handbrake covers, tested and confirmed handbrake switch faulty. Removed drivers seat, replaced complete handbrake handle and tested operation, all ok. Refitted seat as required.

LABOUR Total

Qty	Pkg Part No.	ts and Materials Description
1	OF	OIL FILTER
7.4	SYN	PENRITE DIESEL5 SYN ENGINE OIL
1	SPW	SUMP PLUG WASHER
1	HWD	HAZARDOUS WASTE DISPOSAL
1	EF	ENGINE FLUSH
1	CAB	CABIN FILTER
1	AF	AIR FILTER
1	H7	HALOGEN GLOBE
1	BP	REAR BRAKE PAD SET
2	BD	REAR BRAKE DISC
3	TYRE	KUMHO 215/70R16C 108/106T KC53
1		HANDBRAKE HANDLE ASSEMBLY
1	DD	INWARDS FREIGHT

PARTS Total

INVOICE Total (includir

LE MANS MOTORS SERVICES ABN 59 970 159 478