

EASST Pty Ltd t/as Southside Toyota T 07 3008 6477  
 59 Logan Road, F 07 3008 6479  
 Woolloongabba, QLD 4102 toyota@southsidetoyota.com.au  
 PO Box 1045, Coorparoo DC, QLD 4151 southsidetoyota.com.au

BSB: 014-002 ACC: 372529001  
 ABN: 46 651 942 264 ACN: 651 942 264  
 LMCT: 4565808

REPAIR ORDER No JC14033248	PAGE 1
C1 Customer (Cash)	

Guest <b>SHIVA RANA</b>		DATE 03/05/2024	TIME IN 2:30 PM	TIME OUT 8:30 PM	KILOMETERS 83804	ADVISEP PA	
VEHICLE Corolla Ascent 1.8L Petrol CVT 5 Door Hatch					MONTH/YEAR 08/2017	AIR	
REG No 032104	STOCK No	SELLING DEALER					
GUEST No 22730	VIN JTNKU3JE80J568320			ENGINE No 2ZR1982058			
CONTACT NAME Shiva Rana		COLOUR/TRIM Silver Pearl/Black Fabric			ORDER No		
CONTACT NUMBERS M:0422562932		WAR EXP.	WAR KM	EXT WAR EXP.	EXT WAR KM	RDR Date 18/07/2017	

JOB DETAILS			PRICE	QTY/HRS	AMOUNT	
JOB 1	Carry out 84 months/140,000km service, Toyota Service Guarantee (DAT) From 09/2016 Carried out 84 months/140,000km service, Toyota Service Guarantee. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected cooling system, hoses & connections. Inspected radiator & condenser for debris & signs of damage. Inspected battery electrolyte, cleanliness & security. Inspected air cleaner element. Inspected brake fluid. Inspected brake pads & discs. Checked brake pipes & hoses. Inspected drive shafts including CV boots. Inspected steering wheel, gear & linkages. Inspected ball joints & dust covers. Checked exhaust system for security & leaks. Inspected fuel vapour control valve. Inspected fuel cap, fuel lines & connections. Checked condition & pressures of all tyres including spare. Checked brake pedal height & hand brake lever operation. Checked lights, wiper/washers, horn & electrical systems. Inspected all seat belts operation and condition. Cleaned air conditioning fresh air filter. Inspected air conditioner, including amount of refrigerant. Road tested vehicle & reported any defects.					210.00
PRT	TOY	0888800001C	ORD P/N 0888800001EP	1	.90	
PRT	TOY	9043012031	GASKET	1	1.95	
PRT	TOY	90915YZZN2	MVP OIL FILTER	1	20.78	
CON	Syn Engine Oil 5W30 OE-X				39.02	
<b>JOB 1 SUBTOTAL</b>					<b>272.65</b>	

JOB DETAILS					
JOB 2	DUPLICATE AIR FILTER				NO CHARGE
PRT	TOY	1780121050	ELEMENT SUB-ASSY	1	NO CHARGE
<b>JOB 2 SUBTOTAL</b>					<b>NO CHARGE</b>

\*\*\*\*\* CONTINUED \*\*\*\*\*

**JOB DETAILS**

**VEHICLE RELEASE**

WORK EXPLAINED  
  VEHICLE WASHED  
  FLOOR MAT SECURITY EXPLAINED  
  LETTER  
  PHONE  
  DO NOT CONTACT

COST EXPLAINED  
  ALL COURTESY ITEMS REMOVED  
  EMAIL  
  MOBILE/SMS

pty Ltd t/as Southside Toyota  
 gan Road,  
 olloongabba, QLD 4102  
 O Box 1045, Coorparoo DC, QLD 4151

T 07 3008 6477  
 F 07 3008 6479  
 toyota@southsidetoyota.com.au  
 southsidetoyota.com.au

BSB: 014-002 ACC: 372529001  
 ABN: 46 651 942 264 ACN: 651 942 264  
 LMCT: 4565808

REPAIR ORDER No JC14033246	PAGE 2
C1 Customer (Cash)	

Guest SHIVA RANA		DATE 03/05/2024	TIME IN 2:30 PM	TIME OUT 6:30 PM	KILOMETERS 83804	ADV SER PA	
VEHICLE Corolla Ascent 1.8L Petrol CVT 5 Door Hatc					MONTH/YEAR 06/2017	A/R	
REG No 032104	STOCK No	SELLING DEALER					
GUEST No 22730	VIN JTNKU3JE80J568320			ENGINE No 2ZR1982058			
CONTACT NAME Shiva Rana		COLOUR/TRIM Silver Pearl/Black Fabric			ORDER No		
CONTACT NUMBERS M:0422562932			WAR EXP	WAR KM	EXT WAR EXP	EXT WAR KM	
						RDR Date 18/07/2017	

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 3 VEHICLE REPORT Vehicle Condition Report Battery Report: Passed  Tyre Report: mm  LHF: New RHF: New RHR: New LHR: New  Brake Pads: mm  LHF: New RHF: New RHR: 5 LHR: 5			
Thank you for choosing Southside Toyota for your servicing and repairs.			
JOB 3 SUBTOTAL			NO CHARGE

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 4 Replace 4 Tyres PRT TY TY1111103 TOYO 205/55R16		3	90.00 420.00
JOB 4 SUBTOTAL			510.00

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 5 4 Wheel Alignment Carried out a Wheel Alignment to manufacturer specifications. Adjusted toe, adjusted caster & camber where applicable.			72.27

\*\*\*\*\* CONTINUED \*\*\*\*\*

VEHICLE RELEASE

WORK EXPLAINED     VEHICLE WASHED     FLOOR MAT SECURITY EXPLAINED     COST EXPLAINED  
 LETTER     PHONE     DO NOT CONTACT  
 EMAIL     MOBILE/SMS

Southside Toyota Ltd t/as Southside Toyota  
 Logan Road,  
 Bayside, Brisbane, QLD 4102  
 Box 1045, Coorparoo DC, QLD 4151

T 07 3008 6477  
 F 07 3008 6479  
 toyota@southsidetoyota.com.au  
 southsidetoyota.com.au

BSB: 014-002 ACC: 372529001  
 ABN: 46 651 942 264 ACN: 651 942 264  
 LMCT: 4565808

REPAIR ORDER No JC14033246	PAGE 3
C1 Customer (Cash)	

Guest SHIVA RANA		DATE 03/05/2024	TIME IN: 2:30 PM	TIME OUT: 6:30 PM	KILOMETERS 83804	ADVISER PA
VEHICLE: Corolla Ascent 1.8L Petrol CVT 5 Door Hatch					MONTH/YEAR 06/2017	AIR
REG. No 032104	STOCK No	SELLING DEALER				
GUEST No 22730	VIN JTNKU3JE80J568320	ENGINE No 2ZR1982058				
CONTACT NAME Shiva Rana		COLOUR/TRIM Silver Pearl/Black Fabric		ORDER No.		
CONTACT NUMBERS M:0422562932		WAR. EXP	WAR. KM	EXT WAR EXP	EXT WAR KM	RDR Date 18/07/2017

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 5 SUBTOTAL			72.27
<b>JOB DETAILS</b>			
JOB 7 BUY 4 PAY FOR 3 TYRE DEAL			NO CHARGE
PRT TY TY1111103 TOYO 205/55R16		1	NO CHARGE
JOB 7 SUBTOTAL			NO CHARGE
<b>JOB DETAILS</b>			
JOB 8 Replace front brake pads and rotors			247.50
REPLACED FRONT BRAKE PADS AND FRONT ROTORS			
PRT TOY 04465YZZT8 PAD KIT DISC BRAKE		1	95.45
PRT TOY 4351212670 DISC FR		2	339.40
JOB 8 SUBTOTAL			682.35
<b>JOB DETAILS</b>			
JOB 9 Puncture Repairs (Each)			
CARRIED OUT PUNCTURE REPAIRS TO LHR TYRE (PUT AS SPARE NOW)			
JOB 9 SUBTOTAL			NO CHARGE
<b>JOB DETAILS</b>			
JOB10 Replace Air Cleaner Element			16.50
Replaced air cleaner element.			
PRT TOY 1780121050 ELEMENT SUB-ASSY		1	41.14
JOB 10 SUBTOTAL			57.64

\*\*\*\*\* CONTINUED \*\*\*\*\*

<b>VEHICLE RELEASE</b>		PREFERRED CONTACT METHOD			
<input type="checkbox"/> WORK EXPLAINED	<input type="checkbox"/> VEHICLE WASHED	<input type="checkbox"/> LETTER	<input type="checkbox"/> PHONE	<input type="checkbox"/> DO NOT CONTACT	
<input type="checkbox"/> COST EXPLAINED	<input type="checkbox"/> ALL COURTESY ITEMS REMOVED	<input type="checkbox"/> EMAIL	<input type="checkbox"/> MOBILE/SMS		

Southside Toyota Ltd t/as Southside Toyota  
 1000 Logan Road,  
 Bayside, Brisbane, QLD 4102  
 PO Box 1045, Coorparoo DC, QLD 4151

T 07 3008 6477  
 F 07 3008 6479  
 toyota@southsidetoyota.com.au  
 southsidetoyota.com.au

BSB: 014-002 ACC: 372529001  
 ABN: 46 651 942 264 ACN: 651 942 264  
 LMCT: 4565808

REPAIR ORDER No: JC14033246	PAGE: 4
C1 Customer (Cash)	

Guest: <b>SHIVA RANA</b>		DATE: 03/05/2024	TIME IN: 2:30 PM	TIME OUT: 6:30 PM	KILOMETERS: 83804	ADVISER: PA	
VEHICLE: Corolla Ascent 1.8L Petrol CVT 5 Door Hatch					MONTH/YEAR: 06/2017	AIR:	
REG. No: 032104	STOCK No:	SELLING DEALER:					
GUEST No: 22730	VIN: JTJKU3JE80J568320			ENGINE No: 2ZR1982058			
CONTACT NAME: Shiva Rana		COLOUR/TRIM: Silver Pearl/Black Fabric			ORDER No:		
CONTACT NUMBERS: M:0422562932		WAR. EXP:	WAR. KM:	EXT WAR EXP:	EXT WAR KM:	RDR Date: 18/07/2017	

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
**** Next service due: 03/11/2024 or odometer reading: 94000 whichever comes first.			
LABOUR			\$636.27
CONSUMABLES			\$39.02
PARTS			\$919.62
<b>SUBTOTAL</b>			<b>\$1,594.91</b>
GST			\$159.49
<b>TOTAL INCLUDES GST</b>			<b>\$1,754.40</b>

PRINTED 03/05/24 20:24:07

**VEHICLE RELEASE**

PREFERRED CONTACT METHOD  LETTER  PHONE  DO NOT CONTACT  
 WORK EXPLAINED  VEHICLE WASHED  FLOOR MAT SECURITY EXPLAINED  EMAIL  MOBILE/SMS  
 COST EXPLAINED  ALL COURTESY ITEMS REMOVED