

SERVICE TAX INVOICE

RVICE DEPARTMENT

DDT

TOV

0888800001C

Forsion 49 Avril 9841/22

REPAIR ORDER NO PAGE JC24352093 Customer (Cash)

.90

1

toward a fraction of ABN 99 010 585 252 AU 02316 Customer DATE TIME IN TIME OUT KILOMETERS ADV. SER 2 30 PM 91580 14/03/2024 11 30 AM MR WILL HANRAHAN MONTH/YEAR AIR VEHICLE Unit 9 Hilux 4x2 Workmate 2.7L Petrol Manual Sing 01/2014 220 Kedron Brook Rd SELLING DEALER REG No STOCK No. Wilston QLD 4051 143GJ5 ENGINE No CUSTOMER No. VIN 2TR7692723 155864 MR0CX12G500115266 ORDER No CONTACT NAME Mr Will Hanrahan Sterling Silver/Grey RDR Date CONTACT NUMBERS WAR KM. EXT WAR EXP EXT WAR KM WAR EXP 11/03/2014 M:0437081078 **AMOUNT** QTY/HRS PRICE JOB DETAILS 5.72 JOB 1 TOYOTA FUEL ADDITIVE Added Genuine Toyota Fuel Additive to Tank. 24.28 PRT TOY INJ CLEANER(T) SMALL 0881380019 30.00 JOB 1 SUBTOTAL JOB DETAILS REPLACE A/C POLLEN FILTER JOB 2 73.47 CABIN AIR FILTER 87139YZZ26 PRT TOY JOB 2 SUBTOTAL 73.47 JOB DETAILS CARRY OUT 54 MONTHS/90,000KM SERVICE, TOYOTA SERVICE 154.00 JOB 3 Carried out 54 months/90,000km service, Toyota Service Guarantee. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected brake fluid. Inspected clutch fluid. Inspected battery electrolyte, cleanliness & security. Checked power steering fluid. Inspected brake pads & discs Checked condition & pressures of all tyres including spare. Rotated wheels. Balanced front wheels. Checked lights, wiper/washers, horn & electrical systems. Inspected all seat belts operation and condition. Cleaned air conditioning fresh air filter. Road tested vehicle & reported any defects.

VEHICLE RELEASE			PREFERRED CONTACT METHOD LETTER PHONE DO NOT CONTACT	Т
			CONTINUED	
PRT	TOY	90915YZZD2	OIL FILTER 75*85	22.01
PRT	TOY	9043012031	GASKET 1	1.95
1 1 1 1				

W/SCREEN WASH

VEHICLE RELEASE PREFERRED CONTACT METHO WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXPLAINED	DD LETTER EMAIL	PHONE DO NOT CONTACT MOBILE/SMS
COST EXPLAINED ALL COURTESY ITEMS REMOVED DELIVERED BY DATE	CASH	ACCOUNT EFTPOS/CREDIT CARD
RECEIVED BY TIME AMOUNT RECEIVED WITH THANKS	R	ECEIVED BY



SERVICE TAX INVOICE

SERVICE DEPARTMENT

167	Sa	ndg	ate	Rd.	
-----	----	-----	-----	-----	--

T 07 3000 8000

Albion, QLD 4010

For Service Bookings 3384 5022

torquetoyota com au

RECEIVED BY

TIME

AMOUNT RECEIVED WITH THANKS

REPAIR ORDER NO 2 JC24352093

ABN. 99 010 585 252 AU 02316		C1 Cu	stomer (Cash)	
Customer MR WILL HANRAHAN	DATE 14/03/2024	11:30 AM	2:30 PM	KILOMETERS 91580	ADV SER HW
Unit 9 220 Kedron Brook Rd	Hilux 4x2 Wo	VEHICLE rkmate 2.7L F	etrol Manual	Sing 01/2	17EAR A P
Wilston QLD 4051	REG No. 143GJ5	STOCK No		SELLING DEALE	2
CUSTOMER No 155864 MROCX	12G500115266			2TR7692723	
CONTACT NAME Mr Will Hanrahan	Ste	coLOUR/TRIM erling Silver/Gr	rev	ORDE	ER No
CONTACT NUMBERS M:0437081078	WAR EXP	WAR KM	EXT WAR EXP.	EXT WAR KM	RDR Date 11/03/2014
JOB DETAILS CON 0W-20 Engine Oil MIS Workshop Sundries & Env Levy		PRICE	QTY	/HRS	AMOUNT 50.74 21.54
JOB	3 SUBTOTAL				251.14
JOB DETAILS JOB 4 PAT AIR CONDITIONING SYSTEM AND VENT S Prepared Air Conditioning System for cleaning, indicondition Carried out PAT Air Conditioning System and Ven	luding checking	pollen filter			58.02
PRT NG ANTIMB ANTIMICROBIAL JOB	4 SUBTOTAL			1	21.98 80.00
**** Next service due: 14/09/2024 or odometer reading: 1	100000 whiche	ver comes fi	rst.		
		LABOUR CONSUMAI PARTS MISCELLAI SUBTOTAL GST TOTAL INC	NEOUS		\$217.74 \$50.74 \$144.59 \$21.54 \$434.61 \$43.46 \$478.07
Thank you for servicing your car at Torque Should you have any feedback on your sen please call me. Nathan Visser Service Manager 3384 7930	Toyota Albior vicing experier	n. nce today			
	ONTACT METHOD	LETTER	PHONE	DO NOT CONT	ACT
─ WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXP COST EXPLAINED ALL COURTESY ITEMS REMOVED DELIVERED BY DATE	LAINED	CASH	MOBILE/SMS	EFTPOS/CREDIT (CARD

RECEIVED BY