

Tax Invoice

78 Vore Street, Silverwater NSW 2128

27/03/2024 Invoice no: 756218

Customer:
 LANOUBE PTY LTD
 Remi Noubel
 Burke Cres
 Kingston 2604

Vehicle:
 VOLKSWAGEN GOLF
 1.4L 4CYL FWD PETROL MK6 118TSI
 Speedo: 175200
 Month: 1 Year: 12 Rego: YOE37F
 Vin:WVWZZZ1KZCP105888/

Customers Instructions: Page no:1
 Needed
 Turbo Is Making A Hiss Noise While Driving
 Check Gearbox
 Just Brought Car Want It Checked Over To See If Fluids Are

Work Performed:

 Inspect Vehicle For Whistling Noise. found Turbo Intercooler Pipe Had Popped Off, Upon Inspection Found Seal To Have Failed. supplyband Install New Intercooler Hose. perform Transmission Oil Change.
 Labour
 Repair Call Out

Materials:

 Quote Discount: -0.32
 90.00
 GST 9.00

Section Total 99.00
Additional Repairs Section-A:

 Perform Ultimate Service. This Involved Changing The Engine Oil Using A Quality Oil Suited To Your Vehicle, Replacing The Oil Filter, Performing An Under Bonnet Check And Topping Up All Fluids, Inspecting All Belts And Hoses And Testing The Battery, Checking The Brakes And Suspension, Adjusting The Handbrake Plus Carrying Out A Safety Inspection. The Charging System Was Checked, Cooling System Pressure Tested And A Check Of The Ignition System Was Carried Out. Spark Plugs, Air Filter And Fuel Filter Were Replaced And A Diagnostic Computer Scan And Fault Code Analysis Of Your Engine Management System Was Performed. The Brake Fluid And Cooling System Coolant Were Replaced And Each System Bled. We Also Performed A Prostream Fuel System Intake Decarbonisation. The Vehicle Was Road Tested And A Report Made Of Any Items Found.
 Labour To Remove And Replace:-Drive Belt
 Ultimate Service

Materials:

 Sump Plug Washer 2.95
 Waste Management Levy 12.75
 Van Supplies And Consumables 11.75
 Engine Oil- Penrite Enviroplus Extra (Qty 3.6) 87.26
 Brake Fluid 22.48
 Oil Filter 46.27
 Coolant- Per Litre Concentrate (Qty 2) 33.84
 Spark Plug(Qty 4) 180.56
 Intank Fuel System Cleaner 19.15
 Prostream Intake System Decarb 49.72
 Air Filter 51.96
 Drive Belt 92.50

 1276.22
 GST 127.62

Section Total 1403.84
Additional Repairs Section-B:

Labour

Invoice continued on the next page

Tax Invoice

78 Vore Street, Silverwater NSW 2128

27/03/2024 Invoice no: 756218

Customer:
 LANOUBE PTY LTD
 Remi Noubel
 Burke Cres
 Kingston 2604

Vehicle:
 VOLKSWAGEN GOLF
 1.4L 4CYL FWD PETROL MK6 118TSI
 Speedo: 175200
 Month: 1 Year: 12 Rego: YOE37F
 Vin:WVWZZZ1KZCP105888/



Customers Instructions: Page no:2

 Needed
 Turbo Is Making A Hiss Noise While Driving
 Check Gearbox
 Just Brought Car Want It Checked Over To See If Fluids Are

Materials:	P-trans Fluid-dct Fluid Fs Mv 4l (Qty 2)	272.55
		284.36
		556.91
		GST 55.69
	Section Total	612.60

Additional Repairs Section-C:	Labour To Remove And Replace:-Intercooler Pipe	90.85
Materials:	Intercooler Pipe	375.90
		466.75
		GST 46.68
	Section Total	513.43

Mechanics Report - Road Test Results:
 Road Tested After Work Completed. Vehicle Has Slight Vibration At Cruising Speeds, Recommend Wheel Balance And Alignment.

Brake Wear Report
 Material Left on Pads
 Front: 40% (approx)
 Rear : 50% (approx)
 


Lube Mobile Warranty: Be confident in using Lube Mobile, all work performed and all new parts supplied by Lube Mobile are guaranteed for 12 Months/20,000 km, whichever comes first, by our nationwide Parts and Labour Warranty. Should you ever have any concerns or problems simply give us a call on 13 30 32 from anywhere in Australia. Of course our warranty only applies to work performed by Lube Mobile, the parts we supply and also we must be given first chance of repair.

Signature: _____ Name: :REMI NOUBEL

Phone Approval

27/03/2024--13:09 \$2588.87

 I understand that the above repairs were carried out at my request and also to my satisfaction.
 Paid by: MASTERCARD

Next Service Due: 22/03/2025 . or . 190000 Klms .


 Your Technician
JUSTAN (JW03)
 Ph:0401059150

Customer Discount \$ -40.00

Total \$ 2588.87
 (Includes GST of: \$ 235.35)

less Deposit \$ 860.00

Total Due \$ 1728.87