Uber Carshare

Owner's Service Form

Inspection		Pass Fall
1	BRAKES Right front Right rear Left front Left rear Handbrake	୧୦୦୦୦୦୦ ୦୦୦୦୦୦
2	CLUTCH (manual only)	0 0
3	TYRES Right front Right rear Left front Left rear	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
4	STEERING	Ø 0
5	SUSPENSION Front Rear	8 0 0 0 0 0
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	0000000000000

Inspection		Pass	Fail
7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights	<u> </u>	00000
8	DOORS (open, close, lock)	Ø	0
9	SPEEDOMETER	Ø	0
10	WARNING LIGHTS	Ø	0
11	REAR VIEW MIRRORS	$^{\diamond}$	0
12	SEAT BELTS	Ø	0
13	AIRBAGS	6	0

This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.

PASS

FAIL

1ERRO13 VITO 9 MB 200 CAR REGO CAR MAKE CAR MODEL CAR YEAR Carcare Malaga 245000 **INSPECTION COMPANY NAME** ODO MILEAGE mon **INSPECTOR NAME INSPECTOR SIGNATURE** DATE OF INSPECTION

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should **be completed by qualified** professional mechanics and are only representative of their opinions.