



D.S. Calvert Motors Pty Ltd T/as Essendon Renault
ACN: 111 208 390 **ABN:** 45469763874 **LMCT:** 10092
Sales: 600 Mt Alexander Rd Moonee Ponds Vic 3039
Service & Parts: 411-413 Victoria St Brunswick Vic 3056
T : 03 9080 1111 **F:** 03 9080 1191
E : service@essmtrgrp.com.au
W: www.essendonrenault.com.au

ESSENDON

Service Tax Invoice		Page 1 of 2		Reprint# 1		Doc #: RECSR21093	
Customer No. 19568	Customer Name & Address Mr Abdur Howlader			Advisor Jess W	902	Colour Meissen Blue	Team SERVICE
Doc. Date 26/03/24	[REDACTED]			Year / Make / Model 18/RENAULT/Koleos II Zen 5 Door SUV FWD 2		Tag No.	
Reg. No. 1MM6SR	[REDACTED]			Model No. ZGHGM28N05CC2	Carline KOLEOS		Eng./Trans.
Stock No. N110680	[REDACTED]			Chassis No.	Kilometres 68934	Prod. Date	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer ESSENDON RENAUL	Delivery Kms.	Delivery Date	Warr. Exp. Date 18/04/23
Contact Mobile: [REDACTED]	Engine No. [REDACTED]	Date & Time Promised 26/03/24 12:00pm		Time Received 10:00am	Quote Price	Air	Pwr
Driver: [REDACTED]	Driver Mobile: [REDACTED]		Rego Expiry 12/04/24				
Bus Email:	Email: arhowlader@gmail.com						

Labour	Operation	Description	Units	Amount
Job# 1	01RE95153180N02	180,000km/72mth service {ModelYr: -2019}	Tech(s): 602	315.81

Customer Instructions:

Carried out 180,000km/72 month service as per handbook.
 Road Test.
 Replaced Pollen filter(Every 30,000km).
 Checked for outstanding OTS.
 Installed Seat/Guard/Steering wheel/Floor covers.
 Checked Park light, Stop light, Trafficators, Hi/Lo beam, Hazard, Reverse light, Horn, Fog light, Number plate light,Rev Camera, Fr/Rr Park Sensor before ordering
 Checked levels control of Brake fluid, Coolant, Hydraulic clutch & Power assisted steering before ordering parts.
 Checked function of the handbrake before ordering parts.
 Checked Battery condition with Midtronics (code)..... before ordering parts.
 Checked windscreen wiper/washer condition & operation before ordering parts.
 Checked accessory belt condition/tension before ordering parts.
 Checked computer diagnostic (CLIP) before ordering parts.
 Wear & inflation tyres checked (Customer agreement is required for replacement).
 Checked brake pads, discs before ordering parts(Customer agreement is required for replacement).
 Checked Front & Rear shock absorbers(Customer Agreement is required for replacement).
 Checked Wheel Bearing play.
 Checked Ball joints & suspension bushes(Customer Agreement is required for replacement).
 Checked underneath the body, wheel arches, doors and windows (Customer Agreement is required for replacement).
 Obtained authorisation for additional parts and labour where necessary.
 Replaced the sump drain plug washer.
 Checked leaks in Power assisted steering.
 Checked leaks in Cooling circuit.
 Checked leaks in Brake circuit.
 Checked leaks in Hydraulic clutch.
 Checked leaks in Gearbox.
 Replaced oil filter.
 Replaced air filter @ 24months/30km whichever comes first.
 Filled the sump and checked level.
 Refitted wheels (corrected torque).
 Replaced the Renault Service Sticker.
 Reset the onboard computer for oil change autonomy.
 Before delivery, removed seat/ guard / steering wheel / floor mats.
 Completed Service Book - record section & Quality Control



D.S. Calvert Motors Pty Ltd T/as Essendon Renault
ACN: 111 208 390 **ABN:** 45469763874 **LMCT:** 10092
Sales: 600 Mt Alexander Rd Moonee Ponds Vic 3039
Service & Parts: 411-413 Victoria St Brunswick Vic 3056
T : 03 9080 1111 **F:** 03 9080 1191
E : service@essmtrgrp.com.au
W: www.essendonrenault.com.au

ESSENDON

Service Tax Invoice		Page 2 of 2		Reprint# 1		Doc #: RECSR21093	
Customer No. 19568	Customer Name & Address [REDACTED]	Advisor Jess W	902	Colour Meissen Blue	Team SERVICE	Doc. Date 26/03/24	Tag No.
Reg. No. 1MM6SR	[REDACTED]	Year / Make / Model 18/RENAULT/Koleos II Zen 5 Door SUV FWD 2		Model No. ZGHGM28N05CC2	Carline KOLEOS	Eng./Trans.	
Stock No. N110680	[REDACTED]	Chassis No.	Kilometres 68934	Prod. Date	Orig. Del. Date		
Purchase Order No.	Driver	Contract No.	Contract Name	Contract Exp. Kms	Exp. Date		
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Cash	[REDACTED]	Delivery Kms.	Delivery Date	Warr. Exp. Date 18/04/23
	[REDACTED]	Engine No.	[REDACTED]	Date & Time Promised 26/03/24 12:00pm	Time Received 10:00am	Quote Price	Air Pwr Turb

Certificate.
Checked operation and condition of sliding doors, including hinges and door rollers. (where applicable).
Checked operation of door hinges and latch mechanism.

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	RE1102601M02	WASHER-PLUG	3.43	3.43
Job# 1	1	RE152085758R	FILTER ASSY-OIL	22.00	22.00
Job# 1	1	RE7711238963	SCREEN WASH-	5.13	5.13

Petrol, Oils, Lubricants and Supplies					Amount
Job# 1		Castrol GTX RN17 5W3			110.00
Job# 1		WASTE OIL REMOVAL			15.00
Job# 1		SHOP SUPPLIES			15.00
<<< Total For Job 1 >>>					486.37

Job# 2	02RE95153R15A01		Tech(s): 602		272.74
		Replace Brake Discs and Pads, Front			
Customer Instructions:					
Replaced both front disc brake rotors and brake pads.					
Includes removed and refitted wheels and calipers.					
Carried out final inspection and road test.					
Job# 2	1	RE410601596R	FRT BRAKE PADS	204.54	204.54
Job# 2	2	RE402065HA0A	FRT DISC BRAKE	168.18	336.36
<<< Total For Job 2 >>>					813.64

Misc: RND Rounding -0.01

Comments
|No outstanding campaigns.

Total Labour	588.55
Total Parts	571.46
Total POL	140.00
Total Sublet	0.00
Total Misc	-0.01
Total Tax	130.00
Total Invoice	1430.00