

Brisbane City Mitsubishi



26-44 Burrows Street, Bowen Hills Qld 4006
 PH: (07) 3253 1444 FAX: (07) 3253 1499
Bank Details: CBA **Acct Name:** CBMG North
BSB: 064000 **Acct No:** 14083372

Service TAX Invoice		Page 1 of 3		Reprint# 2		Doc #: MCMC132236	
Customer No. 438667	Customer Name & Address Fabiano Pilati 310/8 Skyring Tce Teneriffe QLD 4005			Advisor BLAIR TANHAM 755	Colour	Team Mitsubis	
Doc. Date 13/12/23				Year / Make / Model 18/MITSUBISHI/XC LS 2.0L PET CVT 2WD			Tag No.
Reg. No. 026YRO				Model No. XC2L45	Carline ASX		Eng./Trans.
Stock No.				Chassis No.	Kilometres 103750	Prod. Date	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone 0420308858	Business Phone	Terms Cash	Selling Dealer	Delivery Kms. 1	Delivery Date 12/10/18	Warr. Exp. Date 11/10/23
	Vehicle ID. JMFXTGA2WJU004583	Engine No.		Date & Time Promised 13/12/23 01:00pm	Time Received 07:30am	Quote Price	Air Pwr Turb
Entity Mobile 0420308858	Driver Ph	Privacy Code			Next Service Date 12/12/24		
Entity Res Email pltfbn@gmail.com	Entity Bus Email						

Labour	Operation	Description	Units	Amount
Job# 1	01MI60354105N05	105,000km/84mth service {ModelYr: 2018-2018}	Tech(s): 360	227.06

Customer Instructions:

Carried out 105,000km/84 month service as per handbook.
 --- Under The Hood ---
 Includes- Replaced engine oil & oil filter.
 Checked all fluid levels & topped up as required.
 Checked drive belt and adjusted tension as required.
 Checked battery terminals for cleanliness & security.
 Checked coolant level & concentration.
 Inspected air filter.
 --- Under The Vehicle ---
 Inspected suspension & steering components for damage/wear.
 Checked under body lines for damage & fluid leaks.
 Inspected drive shafts including CV boots.
 Inspected automatic transmission fluid.
 Inspected ball joints, seals, bushes & boots.
 Inspected brake pads & discs.
 Checked brake hoses & pipes for damage, corrosion & leaks.
 --- Final Inspections & Road Test ---
 Checked brake pedal height & hand brake lever operation.
 Checked engine idle speed.
 Replaced fresh air/pollen filter.
 Inspected air conditioning operation.
 Checked vehicle for outstanding recall or service campaigns.
 Checked all electronic control system diagnosis output using manufacturer specified special tools.
 Road tested vehicle & reported any defects.

Job# 2	10MI60354WBRE0	Rplc Wiper Blade, Rear	Tech(s): 360 357	No Charge
--------	----------------	------------------------	------------------	-----------

Customer Instructions:
 Replaced rear wiper blade.
 Reassembled and tested.

Payment Terms

Authorised Accounts—Strictly 30 days. All other—cash, Visa or Mastercard at or prior to delivery. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair goods. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonable foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Brisbane City Mitsubishi appreciates your custom. Should you not be COMPLETELY SATISFIED with our service, please call our Service Manager on 32531400.

Brisbane City Mitsubishi



26-44 Burrows Street, Bowen Hills Qld 4006
 PH: (07) 3253 1444 FAX: (07) 3253 1499
 Bank Details: CBA Acct Name: CBMG North
 BSB: 064000 Acct No: 14083372

Service TAX Invoice		Page 2 of 3		Reprint# 2		Doc #: MCMMC132236	
Customer No. 438667	Customer Name & Address Fabiano Pilati 310/8 Skyring Tce			Advisor BLAIR TANHAM 755	Colour	Team Mitsubis	
Doc. Date 13/12/23	Teneriffe QLD 4005			Year / Make / Model 18/MITSUBISHI/XC LS 2.0L PET CVT 2WD			Tag No.
Reg. No. 026YRO				Model No. XC2L45	Carline ASX		Eng./Trans.
Stock No.				Chassis No.	Kilometres 103750	Prod. Date	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone 0420308858	Business Phone	Terms Cash	Selling Dealer	Delivery Kms. 1	Delivery Date 12/10/18	Warr. Exp. Date 11/10/23
Vehicle ID. JMFXTGA2WJU004583		Engine No.		Date & Time Promised 13/12/23 01:00pm	Time Received 07:30am	Quote Price	Air Pwr Turb

Total - Labour 227.06

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	MI1230A184	OIL FILTER	24.52	24.52
Job# 1	1	MIMD050317	GASKET-14MM	3.66	3.66
Job# 1	1	MIVS0005871	WASH ADDIT.	0.96	0.96
Job# 1	1	MI7803A109	AIR REFRESHER	66.56	66.56
Job# 1	1	MIAU901582	ENG OIL,A3/B4 10W-	70.00	70.00
Job# 2	1	MIVS000585-1	WIPER BLADE-6MM	11.00	11.00
Job# 2	0	MI8253A093	BLADE ASSY-RR	29.48	0.00

Total - Parts 176.70

Miscellaneous					Amount
Job# 1	M		MI Workshop supplies		8.00
Job# 1	EL		MI ENVIRONMENTAL WASTE DISPOSAL		6.50
Job# A	RND		ROUNDING		0.01

Total - Misc 14.51

Comments

Keys will be in drop box

Recommendations

BOTH REAR TYRES WORN OUT AND REQUIRE REPLACING ASAP

Payment Terms

Authorised Accounts—Strictly 30 days. All other—cash, Visa or Mastercard at or prior to delivery. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair goods. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonable foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Brisbane City Mitsubishi appreciates your custom. Should you not be **COMPLETELY SATISFIED** with our service, please call our Service Manager on 32531400.

Brisbane City Mitsubishi



26-44 Burrows Street, Bowen Hills Qld 4006
 PH: (07) 3253 1444 FAX: (07) 3253 1499
 Bank Details: CBA Acct Name: CBMG North
 BSB: 064000 Acct No: 14083372

Service TAX Invoice		Page 3 of 3		Reprint# 2		Doc #: MCMC132236	
Customer No. 438667	Customer Name & Address Fabiano Pilati 310/8 Skyring Tce			Advisor BLAIR TANHAM 755	Colour	Team Mitsubis	
Doc. Date 13/12/23	Teneriffe QLD 4005			Year / Make / Model 18/MITSUBISHI/XC LS 2.0L PET CVT 2WD			Tag No.
Reg. No. 026YRO				Model No. XC2L45	Carline ASX		Eng./Trans.
Stock No.				Chassis No.	Kilometres 103750	Prod. Date	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone 0420308858	Business Phone	Terms Cash	Selling Dealer	Delivery Kms. 1	Delivery Date 12/10/18	Warr. Exp. Date 11/10/23
Vehicle ID. JMFXTGA2WJU004583		Engine No.		Date & Time Promised 13/12/23 01:00pm	Time Received 07:30am	Quote Price	Air Pwr Turb

Total Labour 227.06
Total Parts 176.70
Total POL 0.00
Total Sublet 0.00
Total Misc 14.51

Total Tax 41.83
Total Invoice 460.10

TOTAL AMOUNT INCLUDING GST

If your vehicle is fitted with a dash cam please check it is functioning prior to leaving as all dash cams will be disconnected during the service/repairs.

Payment Terms

Authorised Accounts—Strictly 30 days. All other—cash, Visa or Mastercard at or prior to delivery. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair goods. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonable foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Brisbane City Mitsubishi appreciates your custom. Should you not be **COMPLETELY SATISFIED** with our service, please call our Service Manager on 32531400.