



A & A CHRISTOU Pty Ltd  
 T/as SOUTH MORANG CAR SERVICE CENTRE  
 UNIT 5, 5 DANAHER DRIVE SOUTH MORANG 3752  
 (03)9404 5500  
 A.B.N. 73 653 928 511

TAX INVOICE SM117147  
 DATE 15-04-2024  
 PAGE 1  
 DOC ID 22058

ACCOUNT NO:

MARSHALL MARSHALL

MAKE SUZUKI  
 MODEL BALENO  
 REGISTRATION 1IS3QZ  
 VIN MA3EWB52S00199048

SOUTH MORANG

INSPECTION REPORT NO.  
 ODOMETER READING 154255

Mobile No.

Order No.

HANDBOOK SERVICE 285.74

|                          |                            |          |       |        |
|--------------------------|----------------------------|----------|-------|--------|
| TWS                      | TRICO WASHER SACHEL        | 1        | 5.00  | 5.00   |
| SP GASKET                | SUMP PLUG WASHER           | 1        | 5.00  | 5.00   |
| MO10/30SS                | 10/30 DURABLEND ENGINE OIL | 3.1      | 13.95 | 43.24  |
| VO40                     | OIL FILTER                 | 1        | 16.50 | 16.50  |
| WA5565                   | AIR FILTER PANEL           | 1        | 48.00 | 48.00  |
| CARRY OUT SERVICE AS DUE | Technician:                | 1.40 Hrs |       | 168.00 |

HANDBOOK SERVICE AS PER MANUFACTURES SPECIFICATIONS  
 REPLACE OIL AND OIL FILTER  
 CHECK ALL LIGHTS  
 CHECK FRONT AND REAR BRAKE PADS  
 CHECK FRONT AND REAR SHOCKER OPERATION AND CONDITION  
 CHECK ALL SUSPENSION  
 CHECK ALL DRIVE BELTS  
 CHECK WASHERS AND WIPERS  
 CHECK TYRES AND TYRE PRESSURES  
 GREASED TAIL SHAFT IF GREASE NIPS FITTED  
 CHECK GEAR BOX OIL LEVEL  
 CHECK DIFF OIL  
 CHECK BRAKE HOSE CONDITION AND BRAKE FLUID  
 CHECK COOLANT SYSTEM AND HOSE  
 CHECK DRIVE SHAFT/AXLE CONDITION  
 ROAD TESTED VEHICLE

REPLACE AIR FILTER

REPORT 0.00

Payment Method Eftpos 295.75