UberCarshare

Owner's Service Form

Inspection		Pass Fail		Inspe	Inspection		Pass	Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake	ABBAAQ	000000	7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights		000000	000000
2	CLUTCH (manual only)	0	0	8	DOORS (open, close,	IOCK)	Ø	0
3	TYRES Right front Right rear Left front Left rear	99999	00000	9 10 11 12	SPEEDOMETER WARNING LIGHTS REAR VIEW MIRRORS SEAT BELTS	;-	Ø Ø Ø	0 0 0
4	STEERING	Ø	0	13	AIRBAGS		Ø	0
5	SUSPENSION Front Rear	8	000					
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	9888888 888888	0000000	m	nis car was inspected echanic listed below asses the checks liste	and satisfact	torily	
YBC26V NISSAN CARREGO CARMAKE AutoCare			Micra CAR MODEL			2013 caryear 34712		
INSPECTION COMPANY NAME		^				ODO MILEAGE		
E	anit	All				29/10/2023		
INSPECTOR NAME IN		ISPECTOR SIGNATURE				DATE OF INSPECTION		

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.