

TAX INVOICE

Tax Invoice Number: [REDACTED]

Date: 07/02/2024

Due Date: 07/02/2024

727 Botany Road
 Rosebery New South Wales 2018
 ABN: 68003150927
 Licence: MVRL52888

BILL TO:

Chris

Tel: [REDACTED]

Email: [REDACTED]

FOR:

Service, rear brakes, wipers, rego

Odometer: 165,573 Kms

Model: Volkswagen Polo

Reg No: CRK81U

VIN: [REDACTED]

Body Type: 4DR Hatch

Year: October 2013

Description	Qty.	Unit Price	Amount
Workshop Consumables Environmental Levy	1.0	[REDACTED]	[REDACTED]
Valvoline SynPower XL3 VW Skoda Audi 5.30	5.0	[REDACTED]	[REDACTED]
Sump Plug Washer	1.0	[REDACTED]	[REDACTED]
Oil filter Z794A Audi VW	1.0	[REDACTED]	[REDACTED]
Air Filter 5185 VW	1.0	[REDACTED]	[REDACTED]
Replace Air Filter			
Cabin AC filter 0217	1.0	[REDACTED]	[REDACTED]
Replace cabin fine particle filter			
Test battery PASS OK!			
SCAN DIAGNOSTIC ECU BCM FAULT FIND RECORD CLEAR RESET			
Wiper Euro Flex 350mm	2.0	[REDACTED]	[REDACTED]
Minor Service Change engine oil & filter. Perform complete vehicle inspection. Check levels, drive belts, wheels, tyres, tyre pressures, brakes, suspension, engine mounts, bushes, wheel bearings, exhaust, drive line, lights, air conditioning, wipers, accessories, test battery.			
Clear Leaves			
Check tyre pressures RESET TPMS ALERT			
Reset service interval display			
Labour service	1.25	[REDACTED]	[REDACTED]
Reset integrated rear brake calliper			
Brake disc rear 08.7165.11 Brembo	2.0	[REDACTED]	[REDACTED]
Replace Rear Brake Disc Rotors			
Brake pads rear 85017 Brembo	1.0	[REDACTED]	[REDACTED]
Replace Rear Brake Pads Grease Slides			
Labour rear brake pads & discs	1.3	[REDACTED]	[REDACTED]
Road Test			
Registration Inspection	1.0	[REDACTED]	[REDACTED]

--

Subtotal	
GST	
Total	
Paid	
Balance Due	

Thanks for choosing us! We appreciate your custom & value your trust. If happy please leave us a good review on google it really helps!

Metro Automotives PTY LTD
BSB: 032 257
ACCOUNT: 521537
BANK: WESTPAC

Authorised Inspection Station e-Safety Check Report



This inspection report shows if the vehicle has passed a NSW Safety Check. It is not a comprehensive report on the vehicle's mechanical condition. Once passed the report is valid for 6 months. However, for the purpose of selling the vehicle the report must not be older than 42 days. For more information contact Transport for NSW on 13 22 13 or visit rms.nsw.gov.au

e-Safety Check number: AS2818852

e-Safety Check status: Pass

Inspection station:

Number: S08492
Name: Metro Auto Repair Centre
Address: 727 Botany Road
ROSEBERY , NSW 2018

Reason for inspection: Registration Renewal

Comment:

Examiner's certification:

I certify that the report is a true record of the vehicle's compliance with the inspection standards of the Rules for Authorised Inspection Stations at the time of inspection.

Examiner's signature:

Examiner's number:

E00219

Inspection date: 07/02/2024

Amount paid: [REDACTED]

Vehicle details:

Number plate: CRK81U
Class: Light Vehicle
Make: VLK
Model: POLO
Odometer reading: 165573
Compliance date: 2 /2014

Renewing registration is easy. Go to myRTA.com

Renewal requirements

- Vehicle requires a valid CTP greenslip. You can then pay online at myRTA.com

Registration renewal payment options



Complete renewal requirements then:



Visit myRTA.com or call 1300 360 782 to obtain BPAY details.



Internet payments: Visit myRTA.com to pay using a valid credit card.



Telephone payments: Phone 1300 360 782 to pay using a valid credit card.



In person: At your nearest registry.

AutoTest
AutoStop Maxi
BRAKE REPORT
Customer Copy
=====
Reg No: CRK81U
Date: 07/Feb/24
Time: 07:25:49
Service Brake
=====
Speed=50 km/h
Stopping Dist=
13.7 m
Decel Avg=0.70 g
Decel Max=1.17 g
MFDD=7.8 m/s
Time=1.88 sec
Pedal Effort
Max=262.4 N
Delay: 0.00 sec
=====
Signature
ID No:
=====
Calibration by
AutoTest
on 12/Jul/2023
Cal Due:
12/Jul/2025
SN: 46766
Version: 8.30
=====
This test is
compliant with
RULE 101.03 & 54
=====