

ABN: 17 115 108 051 Lic No MD 19918 MVRL47274 RTA: AU54621 49 Herbert St, Artarmon, NSW 2064 T: 02 9096 9600

E: service@chatswoodldv.com.au

Mail to: Locked Bag 5110 Parramatta, NSW 2150

EFT Details:

Italian Automobiles Group Pty Ltd BSB: 032-090 ACC: 154885

E: accounts@autoretailgroup.com.au

Service TAX	Invoice Pa	ge 1 of 4					D	oc#: LVCL(21374	9	
Customer No. 33562	Gustomer Name & Addre				Advisor Johan Viljoen	702	Colour 025 Champagne Go		Tean LD'		
Doc. Date	42 Orlagh Cct				Year / Make / Model	Year / Make / Model					
09/05/24	42 Ollagii Oct				17/LDV/SV7A Wagon	17/LDV/SV7A Wagon 7st 5dr SA 6sp 2.0T					
Reg. No.					Model No.		Carline		Eng.	Trans.	
DNE74U					7156NSVBF496700	- 1 -	G10			/Sem	
Stock No. UP4965	Riverstone Nsw	2765			Chassis No.		Glametres 46301	Prod. Date 01/01/17	Orig.	Del. Date	
Purchase Order No.	Driver	Cont		ntract No.	Contract Name	7	Contract Exp. Kms	Exp. Date			
☐ CASH ☐ CHEQUE			ione	Terms Cash	Selling Dealer		Delivery Kms. 33679	Delivery Date 11/05/23	Warr, Exp. Dat		
☐ CREDIT CARD			Engine No EH1S0	GC140303	Date & Time Promised 09/05/24 02:00p		ime Received 07:30am	Quote Price	Air	Pwr Turt	

Labour Description Units Amount Operation

Job#1

01LV86226070N01

70,000km/84mth service

Tech(s): 7018

165.00

TPMS showing wrong wheels

Not callibrated

Calibrate TPMS sensors

Customer Instructions: Carried out 70,000km/84 month service as per handbook.



ABN: 17 115 108 051 Lic No MD 19918 MVRL47274 RTA: AU54621 49 Herbert St, Artarmon, NSW 2064 T: 02 9096 9600

E: service@chatswoodldv.com.au

Mail to: Locked Bag 5110 Parramatta, NSW 2150

EFT Details:

Italian Automobiles Group Pty Ltd BSB: 032-090 ACC: 154885

E: accounts@autoretailgroup.com.au

Service TAX	Invoice Pa	age 2 of 4					Doc #: LVCLO	21374	19			
Customer No. 33562	Customer Name & Add Siddhartha Ma				Advisor Johan Viljoen		lour Champagne Go		Team LDV			
Doc. Date 09/05/24	42 Orlagh Cct				Year / Make / Model 17/LDV/SV7A Wagon 7st 5dr SA 6sp 2.0T					Tag No.		
Reg. No. DNE74U					Model No. 7156NSVBF496700	Garline G10	Eng./Trans. /Sem					
Stock No. UP4965	Riverstone Nsv	w 2765			Chassis No.	Kilometres 46301	Prod. Date 01/01/17	Orig	. Del. I	Date		
Purchase Order No.	Driver		Contract No.		Contract Name	Contract Exp.	Kms Exp. Date					
CASH CHEQUE	Home Phone	one Business Phone		Terms Cash	Selling Dealer	Delivery Kms. 33679	Delivery Date 11/05/23	Warr. Exp. Dat		Date		
CREDIT CARD	The state of the s		Engine No EH1S0	GC140303	Date & Time Promised 09/05/24 02:00pm	Time Received 07:30am	d Quote Price	Air	Pwr	Turb		

Replaced engine oil and oil filter.

--- Checks -

Inspected engine air filter element. Inspected fuel filter.

Inspected pollen/cabin air filter element.

Checked vehicle for outstanding recall or service campaigns.

Checked for diagnostic trouble codes.

Checked brake pedal travel and adjusted as required.

Checked gear lever operation.

Checked gear lever operation.
Checked all interior lighting including dashboard warning lights.
Inspected airbag surfaces for impairment or obstruction.
Inspected seat belts operation and condition.
Inspected and lubricated all latches, hinges and locks.
Checked operation of all exterior lights.
Checked windscreen washer and wiper blades.
Checked better en washer and wiper blades.

Checked battery charge, cleaned and tightened terminals.

Checked windscreen washer fluid level.

Checked brake fluid level.

Checked engine coolant level.

Checked cooling system hoses and fittings.

Checked power steering fluid level.

Checked power steering fluid level.

Checked power steering system hoses and fittings.

Checked air conditioning system hoses and fittings.

Checked intercooler pipe clamps (torque to 5 Nm).

Checked drive belt/s and adjusted tension as required.

Inspected vacuum hoses and connections.

Inspected transmission fluid level.

Inspected crankcase ventilation system.

Inspected tyre condition/wear including spare and adjusted

pressures as required.

Rotated tyres as necessary. Checked and calibrated tyre pressure sensors (if fitted).

Inspected brake pads and disc rotors.

Inspected brake linings and drums (if fitted).
Inspected brake lines, hoses and connections.

Inspected front and rear suspension, tie rod ends, boot seals,

ball joints.

Inspected rear differential for leaks.

Inspected propeller shaft and couplings.

Inspected park brake operation and adjusted as required.

Inspected fuel lines, hoses and connections.

Inspected electrical harnesses for correct routing and damage.

Checked exhaust system for leaks and damage.

Checked all visible underbody parts for leaks and damage. Carried out final inspection and road test.



ABN: 17 115 108 051 Lic No MD 19918 MVRL47274 RTA: AU54621 49 Herbert St, Artarmon, NSW 2064 T: 02 9096 9600

E: service@chatswoodldv.com.au

Mail to: Locked Bag 5110 Parramatta, NSW 2150

EFT Details:

Italian Automobiles Group Pty Ltd BSB: 032-090 ACC: 154885

E; accounts@autoretailgroup.com.au

Service TAX	Invoice Page	e 3 of 4					Do	c #: LVCL0	1374	9	
Customer No. 33562	Customer Name & Address Siddhartha Mazur	=		Advisor Johan Viljoen	7	7025 Colour Cham		our nampagne Go		7	
Doc. Date	42 Orlagh Cct				Year / Make / Model					Tag No.	
09/05/24]			17/LDV/SV7A	Wagon 7st		p 2.0T				
Reg. No. DNE74U				Model No. Carline 7156NSVBF496700 G10				Eng./Trans. /Sem			
Stock No.	-	Chassis No.	30700	G10 Kilometres Prod. Date		Prod. Date	Orig. Del. Date				
UP4965	Riverstone Nsw 2					01/01/17					
Purchase Order No.	Driver Contract No.		Contract Name		Contract Exp. Kms		Exp. Date				
CASH	Home Phone	Business Phone	Terms	Selling Dealer		Delivery Kn	ns.	Delivery Date	Warr.	Exp. Date	
☐ CHEQUE			Cash		33679						
CREDIT CARL			ne No.	Date & Time Promis		Time Recei		Quote Price	Λir	Pwr Tur	
ACCOUNT	LSKG4AL15HA410		11SGC140303	09/05/24	02:00pm	07:30an	n	<u> </u>		40.00	
	LV10105963 LV10105964	(OIL FILTER - ELEN SEAL-OIL FLTR	IENI 6A I		1				18.00 8.7	
	LVALU1403		SUMP PLUG GASK	(ET - COPPER		i			3.1		
Petrol, Oils, L	ubricants and Sup	plies								moun	
lob# 1		SYNPO	WER MST C3 5W30							84.9	
lob# 1		Environ	nental Levey							12.0	
Job# 1		Workst	op Supplies							12.0	
	Misc: WS		Workshop Supplies							12.00	
				Takel Face Jak	_					045.0	
				<< Total For Job	1 >>>					315.82	
lob#2	09LVEL0009	_			Tech(s):	7018				82.50	
			TYRE PRESSURE	LIGHT							
TYRE P	RESSURE MONITOR RESSURE MONITOR TE TPMS			lease							
			<	< Total For Job	2 >>>					82.50	
lob#3	15LVAC0003	,	A/C NOT BLOWING	à AIR	Tech(s):	7018				82.50	
Liquid s AC cont	Rear A/C NOT BLOW pilled over electrical patrol module needs replate Sydney 2-3 DAY's plu	a <i>nel</i> acement									
•			<	< Total For Job	3 >>>					82.5	

Comments

Brakes, Front 6mm, Rear 6mm. Tyres Front 5mm, Rear 5mm. Battery SOH 80%.

Recommendations

88LVZZZZAIRCO - Air Con - Misc



ABN: 17 115 108 051 Lic No MD 19918 MVRL47274 RTA: AU54621 49 Herbert St, Artarmon, NSW 2064

T: 02 9096 9600 E: service@chatswoodldv.com.au Mail to: Locked Bag 5110 Parramatta, NSW 2150

EFT Details:

Italian Automobiles Group Pty Ltd BSB: 032-090 ACC: 154885

E: accounts@autoretailgroup.com.au

Service TAX	Invoice Pag	ge 4 of 4					D	oc#: LVCLC	1374	19
Custamer No. 33562	Customer Name & Addre		Advisor Johan Viljoen	7025	Colour Cham	pagne Go	Tear LD			
Doc. Date	42 Orlagh Cct				Year / Make / Model				Tag	No.
09/05/24					17/LDV/SV7A Wagon 7st 5dr SA 6sp 2.0T					
Reg. No. DNE74U					Model No. 7156NSVBF496700	Carline G10	1			Eng./Trans. /Sem
Stock No. UP4965 Riverstone Nsw 2765				Chassis No.	Kilometra 46301	Kilometres Prod. E 46301 01/0		Orig	Del. Date	
Purchase Order No.	Driver Contract No.			ntract No.	Contract Name	Contract Exp		Exp. Date		
CASH CHEQUE	Home Phone	Business Pho	one	Terms Cash	Selling Dealer		Delivery Kms. Delivery Da 33679 11/05/2			
CREDIT CARD ACCOUNT	Vehicle ID. LSKG4AL15HA41		Engine No EH1S	o. GC140303	Date & Time Promised 09/05/24 02:00pm	Time Red 07:30a		Quote Price	Air	Pwr Turi

Total Labour	330.00
Total Parts	29.87
Total POL	108.95
Total Sublet	0.00
Total Misc	12.00
Total Tax	48.08
TOTAL LAX	40.00
Total Invoice	528.90

TAX INVOICE