

Werribee MG

187-189 Old Geelong Road, Hoppers Crossing, Vic 3029
 PO Box: 4027, Hoppers Crossing, Vic 3029
 Ph: (03) 9974 3799 Fax: (03) 9749 4388
 Email: service@werribeemg.com.au
 Web: www.werribeemg.com.au
 LMCT# 9800



Western MG

3 Eucumbene Drive Ravenhall Vic 3023
 PO Box: 2151, Deer Park North Vic 3029
 Ph: (03) 9974 5777 Fax: (03) 9217 8688
 Email: service@westernmg.com.au
 Web: www.westernmg.com.au
 LMCT# 9800

Service TAX Invoice		Page 1 of 2		Doc #: MWCW80101			
Customer No. 247566	Customer Name & Address Jebali Rime 1b Keeron St Caulfield South VIC 3162			Advisor Nez Dogu 8643	Colour black pebble	Team Western	
Doc. Date 02/02/24				Year / Make / Model 23/MG/MG3 EXCITE Sat Nav 1.5L 4Spd Auto H		Tag No. 14	
Reg. No. 1ZE2QW				Model No. MG34ATEXCT23SN	Carline MG3		Eng./Trans. /a
Stock No. 033627				Chassis No.	Kilometres 2234	Prod. Date 31/01/23	Orig. Del. Date 19/12/23
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 19/12/23	Warr. Exp. Date 08/12/30
	Vehicle ID. LSJZ14U97PS033627	Engine No. 15S4C5TGNC231374		Date & Time Promised 02/02/24 11:00am	Time Received 07:30am	Quote Price	Air Y
Ent Mob# 0412363819	Priv Email fouad142@hotmail.com		Bus Email		Driver Ph#		

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 1	01MGZZZZ1000	1000 Km Inspection	Tech(s): 8636	Internal
--------	--------------	--------------------	---------------	----------

Customer Instructions:
 Carried Out Manufacturer Recommended Service
 Checked & topped up all fluid levels
 Checked condition of battery, cleaned & tightened battery terminals.
 Checked vehicle for any outstanding Campaigns
 Checked handbrake operation and adjusted as necessary
 Checked operation of lighting system
 Inspected Wheels and Tyre condition
 Check vehicle systems operation via MG Diagnostic Machine
 Inspected condition of cooling system, coolant level, check for leaks & condition of hoses
 Lubricated Bonnet Lock and Safety Catch
 Inspected condition of wiper blades
 Inspected operation of windscreen washer system
 Carried out road test of vehicle

Job# 2	88MGZZZZZ001	Miscellaneous Repair	Tech(s): 8636	Internal
--------	--------------	----------------------	---------------	----------

Left rear making noise - INSPECT
 Road test vehicle and could not duplicate customer concern.
 Customer to demonstrate.

TERMS AND CONDITIONS

In the event that payment for goods and services is not paid and it is necessary to engage a mercantile agent to recover costs, the company/partnership and the guarantors hereby acknowledge that in addition to payment for goods and services they will also be responsible for the reasonable collection costs incurred by the company in the recovery of monies due. This service invoice has been explained and handed over. I have received my vehicle in good order.
 Our services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:
 1. to cancel your service contract with us; and 2. to a refund for the unused portion, or to compensation for its reduced value.
 You are also entitled to be compensated for any other reasonably foreseeable loss or damage. If the failure does not amount to a major failure you are entitled to have problems with the service rectified in a reasonable time and, if this is not done, to cancel your contract and obtain a refund for the unused portion of the contract.

RETENTION OF TITLE

Until payment in full Title to the goods shall remain with the company although risk shall pass to the Customer upon delivery. The Customer shall hold the goods as bailee for the Company. If the Customer defaults in any way then the Company may relake possession of any of its goods which have been supplied and for which payment has not been received and for this purpose the Company may enter any premises belonging to or occupied by the Customer for the purpose of relaking possession of its goods.

PAYMENT TERMS

Trading terms are Net 21 Days. Failure to adhere to these terms the account will become C.O.D./ until such time as the account is paid in full.
 Credit Card Surcharge - VISA & Mastercard 1.2% and Amex 1.5%

Customer Signature Date

I/We are satisfied with the explanation of the work and costs related to this service.					
Customer Signature					
<input type="checkbox"/> Cash	<input type="checkbox"/> Visa Card	<input type="checkbox"/> Master Card	<input type="checkbox"/> Amex	<input type="checkbox"/> Other	




Billor Code 31369
 Ref. No 2475663

Please email remittance advice to
 accounts@westernautomotivegroup.com.au

Werribee MG

187-189 Old Geelong Road, Hoppers Crossing, Vic 3029
 PO Box: 4027, Hoppers Crossing, Vic 3029
 Ph: (03) 9974 3799 Fax: (03) 9749 4388
 Email: service@werribeemg.com.au
 Web: www.werribeemg.com.au
 LMCT# 9800



Western MG

3 Eucumbene Drive Ravenhall Vic 3023
 PO Box: 2151, Deer Park North Vic 3029
 Ph: (03) 9974 5777 Fax: (03) 9217 8688
 Email: service@westernmg.com.au
 Web: www.westernmg.com.au
 LMCT# 9800

Service TAX Invoice				Page 2 of 2				Doc #: MWCW80101					
Customer No. 247566	Customer Name & Address Jebali Rime 1b Keeron St Caulfield South VIC 3162			Advisor Nez Dogu 8643	Colour black pebble	Team Western		Doc. Date 02/02/24	Year / Make / Model 23/MG/MG3 EXCITE Sat Nav 1.5L 4Spd Auto H			Tag No. 14	
Reg. No. 1ZE2QW				Model No. MG34ATEXCT23SN	Carline MG3		Eng./Trans. /a	Stock No. 033627	Chassis No.		Kilometres 2234	Prod. Date 31/01/23	Orig. Del. Date 19/12/23
Purchase Order No.	Driver	Contract No.		Contract Name		Contract Exp. Kms	Exp. Date						
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer		Delivery Kms.	Delivery Date 19/12/23	Warr. Exp. Date 08/12/30					
		Vehicle ID. LSJZ14U97PS033627	Engine No. 15S4C5TGNC231374	Date & Time Promised 02/02/24 11:00am		Time Received 07:30am	Quote Price	Air Y	Pwr Y	Turb N			

Total Labour 0.00
Total Parts 0.00
Total POL 0.00
Total Sublet 0.00
Total Misc 0.00

Total Tax 0.00
Total Invoice 0.00

TOTAL AMOUNT INCLUDING GST

All New MG ZS Available, Enquire now.
 Contact our sale team on 9974 3799

TERMS AND CONDITIONS

In the event that payment for goods and services is not paid and it is necessary to engage a mercantile agent to recover costs, the company/partnership and the guarantors hereby acknowledge that in addition to payment for goods and services they will also be responsible for the reasonable collection costs incurred by the company in the recovery of monies due. This service invoice has been explained and handed over. I have received my vehicle in good order.

Our services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:

1. to cancel your service contract with us; and 2. to a refund for the unused portion, or to compensation for its reduced value.

You are also entitled to be compensated for any other reasonably foreseeable loss or damage. If the failure does not amount to a major failure you are entitled to have problems with the service rectified in a reasonable time and, if this is not done, to cancel your contract and obtain a refund for the unused portion of the contract.

RETENTION OF TITLE

Until payment in full Title to the goods shall remain with the company although risk shall pass to the Customer upon delivery. The Customer shall hold the goods as bailee for the Company. If the Customer defaults in any way then the Company may retake possession of any of its goods which have been supplied and for which payment has not been received and for this purpose the Company may enter any premises belonging to or occupied by the Customer for the purpose of retaking possession of its goods.

PAYMENT TERMS

Trading terms are Net 21 Days. Failure to adhere to these terms the account will become C.O.D./ until such time as the account is paid in full.

Credit Card Surcharge - VISA & Mastercard 1.2% and Amex 1.5%

Customer Signature

Date

I/We are satisfied with the explanation of the work and costs related to this service.

Customer Signature

Cash	Visa Card	Master Card	Amex	Other
------	-----------	-------------	------	-------



Billor Code 31369
 Ref. No 2475663

Please email remittance advice to
 accounts@westernautomotivegroup.com.au