

NAB FFTPOS  
RDS MOTOR GROUP  
PRESTON AU  
MID: 33195017  
TID: M3YF49  
Version: 0.10.030

957 676  
Mitsubishi LMCT 11438  
Victoria 3072  
2



**CUSTOMER COPY**  
JAN 04, 24 17:31  
BATCH: 000403  
INV: 4551  
STAN: 005359  
ACCOUNT TYPE CRID11  
RRN: 000403004551  
MASTERCARD  
A0000000041010  
MASTERCARD  
.....9184(1)  
SALE AUD \$299.00

APPROVED 00  
APPROVAL CODE 021290  
ARQC: CBB77054FB692244  
APSN:00 ATC:0040

PLEASE RETAIN RECEIPT  
FOR YOUR RECORDS

Doc #: MIYMH128758		Team	Mitsubis
Advisor		Tag No	38
Shanaie Lyons	3464	Colour	WHITE/BLACK
Year / Make / Model		Eng / Trans.	/A
21/MITSUBISHI/YB Eclipse Cross LS 2WD 1.5		Orig. Del. Date	06/05/21
Model No	Carline		
YB2L45	YB ECLIPSE		
Chassis No	Kilometres	Prod Date	30/03/21
Z004108	75232	Exp Date	
Contract No.	Contract Name	Contract Exp. Kms	Exp Date
		Delivery Kms.	Delivery Date
Phone	Terms	Selling Dealer	342
	Cash	Date & Time Promised	04/01/24 05:00pm
Engine No.	4B40 JJ5406	Time Received	08:00am
AMIN.30@HOTMAIL.COM		Quote Price	
DRIVERS MOBILE		Warr. Exp. Date	
		Air	Pwr
		Turbo	

**Description**

**Amount**

115.59

01MI92066075N01

75,000km/60mth service {ModelYr: 2021-2022}

Tech(s): 3007

**Customer Instructions:**

- Carried out 75,000km/60 month service as per handbook.
- Under The Hood ---
- Replaced engine oil and oil filter.
- Checked drive belt and adjusted tension as required.
- Inspected valve clearances (audible check only), adjust if necessary.
- Checked brake fluid level.
- Checked coolant level.
- Checked air cleaner element for clogging and damage.
- Checked battery terminals for cleanliness and security.
- Checked battery electrolyte specific gravity, level and condition using specified tools.
- Checked EGR system.
- Under The Vehicle ---
- Inspected suspension and steering components for damage/wear.
- Inspected ball joints, seals, bushes and boots.
- Inspected CVT transmission fluid level.
- Inspected drive shafts including CV boots.
- Checked under body for damage and condition.
- Inside The Vehicle ---
- Checked the free play and operation of the brake pedal, adjust if required.
- Checked and adjusted park brake as required.
- Replaced fresh air/pollen filter.
- Outside The Vehicle ---
- Checked brake hoses and pipes for damage, corrosion and leaks.
- Inspected brake pads and discs.
- Final Inspections and Road Test ---
- Inspected the body of the vehicle for any damage.
- Checked condition and pressures of all tyres including spare.
- Checked lights, wiper/washers, horn and electrical systems.
- Inspected seat belts.
- Inspected air conditioning operation.
- Checked vehicle for outstanding recall or service campaigns.
- Checked all electronic control system diagnosis output using manufacturer specified special tools.
- Reset service indicator.
- Road tested vehicle and reported any defects.
- Subsidised by MITS CPS

MI7803A109	AIR REFRESHER ASSY	1	
MIMD050317	GASKET-14MM	1	68.76
MI1230A184	OIL FILTER	1	3.82
MIMZ691137S	WASHER ADDITIVE, 1 off (Pricin	1	25.33
POL	MOBIL S 5W/30	4.3	1.00
POL	ENVIRONMENTAL LEVY	1.0	47.30
POL	WORKSHOP SUPPLIES	1.0	5.00
Misc:MIWPS	Mitsubishi CPS Contribution		5.00

Warranty

...d.  
 119 957 676  
 Mitsubishi LMCT 11438  
 ...reston, Victoria 3072  
 ...n Victoria 3072  
 ...0500  
 ...a.com.au  
 ...ce.MI@ralphdsilva.com.au



Customer No. 212854	Customer Name & Address Mr MOHAMED S A ELAMIN Unit 102		Advisor Shanaie Lyons		Doc #: MIYMH128758	Team Mitsubis
Doc Date 04/01/24	55 Oleander Dr		Year / Make / Model 21/MITSUBISHI/YB Eclipse Cross LS 2WD 1.5	Colour 3464 WHITE/BLACK	Tag No 38	Eng / Trans /A
Reg No 1TQ2TM	MILL PARK VIC 3082		Model No YB2L45	Carline YB ECLIPSE	Orig Del Date 06/05/21	
Stock No. 2679609	Driver	Contract No.	Chassis No. Z004108	Kilometres 75232	Prod Date 30/03/21	
Purchase Order No.	Home Phone	Business Phone	Contract Name	Contract Exp Kms	Exp Date	Warr. Exp Date
<input type="checkbox"/> Cash <input type="checkbox"/> Cheque <input type="checkbox"/> Credit Card <input type="checkbox"/> Account	Vehicle ID. JMFXTGK1WMZ004108	Engine No. 4B40 JJ5406	Selling Dealer 342	Delivery Kms	Delivery Date 06/05/21	Air Pwr Turbo
			Date & Time Promised 04/01/24 05:00pm	Time Received 08:00am	Quote Price	

<<< Total For Job 1 >>>

271.80

Job# 2 14MIZZZZZZ LOAN VEHICLE Tech(s): 6010 No Charge  
 Job# 3 88MIZZDIAG1 DIAGNOSIS Tech(s): 6010 No Charge

Customer was driving vehicle when abs came on all of a sudden  
 Please inspect  
 Checked and unable to fault the system  
 Misc:RND ROUNDDING

0.02

Total Labour	115.59
Total Parts	98.91
Total POL	57.30
Total Sublet	0.00
Total Misc	0.02
Total Tax	27.18
<b>Total Invoice</b>	<b>299.00</b>

TOTAL INCLUDING GST

"Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:  
 • to cancel your service contract with us; and  
 • to a refund for the unused portion, or to compensation for its reduced value.  
 You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service."

Non genuine parts are identified by the prefix NG or AC. These parts are not covered by vehicle manufacturer's parts and accessory warranty provided by the vehicle manufacturer for your vehicle