Uber Carshare

Owner's Service Form

							- "	
Inspection		Pass	Fail	Insp	ection	Pass	Fail	
1	BRAKES	d	0	7	LIGHTS	Ø	0	
	Right front	Ø	0		Headlights	Ø	0	
	Right rear	Q	0		Turn indicator lights	O	0	
	Left front	Ø	0		Brake lights	Q	0	
	Left rear	Ø	0		Tail lights	Q	0	
	Handbrake	Ø	0	8	DOORS (open, close, lock)	Ø	0	
2	OLUTOU (manual anha)	0-	-	0	books (open, close, lock)			
2	CLUTCH (manual only)			9	SPEEDOMETER	Q	0	
3	TYRES	Ø	0			-/	0	
	Right front	Q	0	10	WARNING LIGHTS	(V)	0	
	Right rear	Ø	0	11	REAR VIEW MIRRORS	OV.	0	
	Left front	Ø	0	11	REAR VIEW WIRRORS			
	Left rear	0/	0	12	SEAT BELTS	Ø	0	
4	STEERING	0	0	13	AIRBAGS	Q/	0	
5	SUSPENSION	Ø	0					
	Front	Ø	0					
	Rear	0	0					
6	WINDSCREEN	Ø	0	T	ais car was inspected by the gu	alified		
0	Large crack (+3cm)= Fail	Ø	0		This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.			
	Small crack (-3cm)= Pass	0	0					
	Front glass	0	0	P				
	Front wipers	Or	0		PA	SS FAI	L	
	Rear glass	d	0			XC)	
	Rear wiper (if available	0/	0					

810TUD	Holden	Captiva	2014
CARREGO FRIEDER	CAR YEAR 161323		
INSPECTION COMPA Friederi		faint	ODO MILEAGE
INSPECTOR NAME		OR SIGNATURE)	DATE OF INSPECTION

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.