UberCarshare

Owner's Service Form

Inspe	ection	Pass Fail	Inspection	Pass Fail
1	BRAKES	Ø. 0	7 LIGHTS	Ø 0
	Right front		Headlights	0/,0
	Right rear	0/0	Turn indicator lights	0/0
	Left front	0,0	Brake lights	0/0
	Left rear	0,0	Tail lights	Ø 0
	Handbrake	Ø 0		
_			8 DOORS (open, close, lock)	Ja & O
2	CLUTCH (manual only) NA	0	+ rem	
3	TYRES	Ø, 0	9 SPEEDOMETER	9 0
	Right front		10 WARNING LIGHTS	q'
	Right rear	000		1 /
	Left front	0, 0	11 REAR VIEW MIRRORS MANY	4 00
	Left rear	ø/ ö		0/0
		,	12 SEAT BELTS X >	o ⁄ o
4	STEERING	\varnothing	13 AIRBAGS - no recal - no warm	1 00
5	SUSPENSION	~ ~	12 Work	vian
3	Front	Ø O	119	Won.
	Rear	Ø 0	,	
	156			
6	WINDSCREEN	0/0	This car was inspected by the	gualified
	Large crack (+3cm)= Fail	Ø 0	mechanic listed below and sat	
	Small crack (-3cm)= Pass	0/0	passes the checks listed on thi	•
	Front glass	Q 0		PASS , FAIL
	Front wipers	0	PRECISION	CASS FAIL
	Rear glass	80	GERMAN PRECISION	\otimes \bigcirc
	Rear wiper (if available 🗸	Q O	VEHICLE INSPECTIONS Prepurchase check/services	
			Mont Albert North 3129	
			prepurchasecheck.com.au	
	15111		<u></u>	-06
<u>U</u>	LJ554 HONDA	JP	122 VTi 2	006
CAR	REGO CAR MAKE		CAR MODEL CAR YE	AR
GERI	MAN PRECISION VEH	ICLE IN	ISPECTIONS 18	32493
INSPECTION COMPANY NAME ODO MILEAGE				
	LLAUS STURM	112 5	9-	-2-2024
INSPECTOR NAME INSPECTOR SIGNATURE DATE OF INSPECTION				