

GILLEN MOTORS PTY LTD T/A
 A.B.N. 31 002 555 811
 LICENCED MOTOR DEALER LIC.NO. 11013
 ARC AUTHORISATION NUMBER AU02348

**644 Parramatta Road
 Croydon NSW 2132**

**PHONE: (02) 8799-7577
 EMAIL: (02) 9799-4615**

Service TAX Invoice				Page 1 of 2				Doc #: HFCSF595985					
Customer No. 540517	Customer Name & Address Passawit Maneerod Unit 203			Advisor ANDREW FISHER 1833		Colour CRIMSON RED/		Team SERVICE					
Doc. Date 07/09/23	1 McKinnon Ave			Year / Make / Model 22/HYUNDAI/Tucson 5 Door SUV AWD 2.0Lt CD				Tag No. 15					
Reg. No. YMA01Q	Five Dock NSW 2046			Model No. GWWD2RC5K		Carline TUCSON		Eng./Trans. 2.0D/A					
Stock No. 220518387				Chassis No.		Kilometres 25441	Prod. Date 26/07/22	Orig. Del. Date 30/09/22					
Purchase Order No.	Driver		Contract No.		Contract Name		Contract Exp. Kms		Exp. Date				
	Home Phone 0401885405	Business Phone	Terms Cash		Selling Dealer H2132V PHIL GILBERT CROYDON		Delivery Kms.		Delivery Date 30/09/22		Warr. Exp. Date 29/09/27		
	Vehicle ID. KMHJC81CSNU172733		Engine No. D4HDNH735649		Date & Time Promised 07/09/23 11:00am		Time Received 07:40am		Quote Price		Air Y	Pwr Y	Turbo Y

Labour Operation Description Amount

Job# 1 01HY94553015H01 15,000km/12mth iCare 5 Year Service Plan Tech(s): 1846 1753 1624 141.54

Customer Instructions:

Carried out 12 month/15,000 km Hyundai iCare 5 Year Service Plan.
 Hyundai iCare Roadside Assist - Complimentary
 Hyundai iCare MapCare (if applicable) - Complimentary
 --- Cabin & Surrounds ---
 Checked vehicle for outstanding recall or service campaigns.
 Carried out complete Global Diagnostic System (GDS) check.
 Checked instrument cluster & warning lights.
 Checked lights, wiper/washers, horn & electrical systems.
 Inspected seat belts.
 Inspected SRS airbag & pre-tensioner.
 Checked & lubricated hood latch, safety catch & hinges.
 Inspected pollen filter.
 --- Engine Bay ---
 Checked air-conditioning system operation.
 Replaced engine oil & oil filter.
 Inspected battery electrolyte, cleanliness & security.
 Checked air filter.
 Inspected brake fluid *replaced if required.
 --- Under Vehicle ---
 Checked condition & pressures of all tyres including spare.
 Rotated wheels following manufacturers recommended sequence.
 Inspected brake pads, calipers & discs.
 Inspected park brake operation & adjusted as required.
 Inspected brake lines & hoses.
 Inspected steering gear, linkage & boots.
 Inspected front suspension & ball joints.

*Additional charges will apply if replacement is required.

HY263202R000	SERVICE KIT-OIL FILTER	1	43.41
HY2151323001	GASKET-OIL PLUG	1	3.33
HYAL009M0002	HYUNDAI INJECTOR CLEANER-	1	10.48
POL	Magnatec Prof C2 5w-30		133.00
Misc:WD	ENVIRONMENTAL WASTE DISPOSAL		9.15

<<< Total For Job 1 >>>

340.91



SERVICE DEPARTMENT

GILLEN MOTORS PTY LTD T/A
 A.B.N. 31 002 555 811
 LICENCED MOTOR DEALER LIC.NO. 11013
 ARC AUTHORISATION NUMBER AU02348

**644 Parramatta Road
 Croydon NSW 2132**

**PHONE: (02) 8799-7577
 EMAIL: (02) 9799-4615**

Service TAX Invoice				Page 2 of 2				Doc #: HFCSF595985			
Customer No. 540517	Customer Name & Address Passawit Maneerod Unit 203			Advisor ANDREW FISHER	1833	Colour CRIMSON RED/	Team SERVICE				
Doc. Date 07/09/23	1 McKinnon Ave			Year / Make / Model 22/HYUNDAI/Tucson 5 Door SUV AWD 2.0Lt CD			Tag No. 15				
Reg. No. YMA01Q	Five Dock NSW 2046			Model No. GWWD2RC5K	Carline TUCSON			Eng./Trans. 2.0D/A			
Stock No. 220518387				Chassis No.	Kilometres 25441	Prod. Date 26/07/22	Orig. Del. Date 30/09/22				
Purchase Order No.	Driver	Contract No.		Contract Name		Contract Exp. Kms	Exp. Date				
	Home Phone 0401885405	Business Phone	Terms Cash	Selling Dealer H2132V PHIL GILBERT CROYDON		Delivery Kms.	Delivery Date 30/09/22	Warr. Exp. Date 29/09/27			
	Vehicle ID. KMHJC81CSNU172733	Engine No. D4HDNH735649		Date & Time Promised 07/09/23 11:00am	Time Received 07:40am	Quote Price	Air Y	Pwr Y	Turbo Y		

Labour	Operation	Description	Amount
Job# 2	55HYZZ18	Hyundai Map Care	Tech(s): 1709 0.00
		Perform Sat Nav Map Upgrade (if fitted). Record SW & Map version prior to update.	
		Carried out Sat/Nav Update (Valued at \$150.00)-Complimentary	
		<<< Total For Job 2 >>>	0.00
Job# 3	44HYZZ02	Balance Front Wheels	Tech(s): 1846 28.18
		Recommended	
		<<< Total For Job 3 >>>	28.18
Job# 4	18HY94553PFIL01	Rplc Fresh Air/Pollen Filter	Tech(s): 1624 30.00
		Customer Instructions: Replaced cabin air/pollen filter. HY97133N9100	
		FILTER ASSY-AIR	1 69.50
		<<< Total For Job 4 >>>	99.50
Job# 5	55HYZZ14	Roadside Assist - Standard	Tech(s): 1709 0.00
		12MTH HYUNDAI ROADSIDE SUPPORT PLAN (VALUED AT \$100) We have provided you with complimentary Hyundai Roadside Assistance (Valued at \$100.00).This will be renewed	
		<<< Total For Job 5 >>>	0.00
	Misc:RND	ROUND UP/DOWN	0.02
	Misc:CC	C/CARD SURCHARGE	2.12
	Comments	Brake report. Front 7mm and rear 8mm.	



SERVICE DEPARTMENT

GILLEN MOTORS PTY LTD T/A
 A.B.N. 31 002 555 811
 LICENCED MOTOR DEALER LIC.NO. 11013
 ARC AUTHORISATION NUMBER AU02348

**644 Parramatta Road
 Croydon NSW 2132**

**PHONE: (02) 8799-7577
 EMAIL: (02) 9799-4615**

Service TAX Invoice				Page 3 of 2		Doc #: HFCSF595985			
Customer No. 540517	Customer Name & Address Passawit Maneerod Unit 203			Advisor ANDREW FISHER	1833	Colour CRIMSON RED/	Team SERVICE		
Doc. Date 07/09/23				Year / Make / Model 22/HYUNDAI/Tucson 5 Door SUV AWD 2.0Lt CD		Tag No. 15			
Reg. No. YMA01Q	1 McKinnon Ave			Model No. GWWD2RC5K	Carline TUCSON		Eng./Trans. 2.0D/A		
Stock No. 220518387	Five Dock NSW 2046			Chassis No.	Kilometres 25441	Prod. Date 26/07/22	Orig. Del. Date 30/09/22		
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date			
	Home Phone 0401885405	Business Phone	Terms Cash	Selling Dealer H2132V PHIL GILBERT CROYDON	Delivery Kms.	Delivery Date 30/09/22	Warr. Exp. Date 29/09/27		
	Vehicle ID. KMHJC81CSNU172733	Engine No. D4HDNH735649		Date & Time Promised 07/09/23 11:00am	Time Received 07:40am	Quote Price	Air Y	Pwr Y	Turbo Y


Total Labour	199.72
Total Parts	126.72
Total POL	133.00
Total Sublet	0.00
Total Misc	11.29
Total Tax	47.07

TOTAL AMOUNT INCLUDING GST

Total Invoice 517.80

Thank you for choosing Phil Gilbert Croydon

Next Service Due.....of.....



WIN A \$500 SERVICE CREDIT*

EXCLUSIVE TO PHIL GILBERT HYUNDAI, SIMPLY FILL OUT THE SURVEY ARRIVING IN YOUR EMAIL INBOX SHORTLY AND GO IN THE DRAW

You may receive a survey from Hyundai asking you to rate your recent service experience. Simply complete the survey to go in the running to win a \$500 service credit*. If you feel we did not provide a 10/10 experience, please contact us. See the manufacturer's scoring system below.



*Each eligible guest who completes a Hyundai Survey CS survey in their own name will receive one entry per survey in the month of completion to win 1 x Phil Gilbert Hyundai service department credit to the value of \$500.00 for use on services on the vehicle to which the survey relates. Service credits can only be used at Phil Gilbert Hyundai service locations at Lidcombe and Croydon. Service credits are valid for 2 years from the date of the prize draw; and Service credits are not transferable or redeemable for cash. See full terms and conditions at http://bit.ly/Service_Comp

Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:

- to cancel your service contract with us; and

- to a refund for the unused portion, or to compensation for its reduced value.

You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is

not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion.

You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service.