## **Uber** Carshare

## Owner's Service Form

| Inspection |   | Pass Fail                             | Inspection   | Pass Fail          |
|------------|---|---------------------------------------|--|--------------------|
| 1          | BRAKES Right front Right rear Left front Left rear Handbrake  |                                       | 7 LIGHTS Headlights Turn indicator lights Brake lights Tail lights  8 DOORS (open, close, lock)                                    | 000000             |
| 2          | CLUTCH (manual only)  | 0 0                                   | 9 SPEEDOMETER  | <b>V</b> 0         |
| 3          | TYRES Right front Right rear Left front Left rear   | 0<br>0<br>0<br>0<br>0                 | 10 WARNING LIGHTS 11 REAR VIEW MIRRORS 12 SEAT BELTS   | <ul><li></li></ul> |
| 4          | STEERING  | <b>√</b> 0                            | 13 AIRBAGS   | <b>√</b> 0         |
| 5          | SUSPENSION<br>Front<br>Rear   | 0<br>0<br>0                           |  |                    |
| 6          | WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available | 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.  PASS FAIL |                    |

| CAR REGO<br>CSK93V | CAR MAKE<br>Skoda         | CAR MODEL Yeti 2.0 TDI 4x4 auto | CAR YEAR<br>2014   |
|--------------------|---------------------------|---------------------------------|--------------------|
| INSPECTION COMPA   | ODO MILEAGE<br>140,950 km |                                 |                    |
| INSPECTOR NAME     | INS                       | SPECTOR SIGNATURE               | DATE OF INSPECTION |
| Colum Crawford     |                           | <u>(0</u>                       | 19/02/2024         |

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

## **Vehicle Service Record**

- Engine flush, oil & filter (5W-30 VW504/507)
- DSG gearbox oil & filter (DCT oil)
- Haldex differential oil (genuine VW)
- Brake fluid
- Timing belt & water pump
- Auxiliary drive belt
- Cabin filter
- Front wiper & rear blades
- Windscreen washer fluid
- Tyre pressures

## **Notes**

- Front brake pads to be replaced at next service
- No damage to bodywork
- · Radio head unit replaced
- Ĭ